Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--
VIN: MDHZBAAD0Z0513822

Odometer Reading: 167836km
License Plate: KF70CTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
Engine	1
ABS	2
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	3
BCM	4
IPDM E/R	2

DTC (12)

Engine (1 DTC)

DTC	Description	Status
P0136	Heated Oxygen Sensor (HO2S)2 (bank1)	Current

ABS (2 DTCs)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past
U1002	System communication (CAN)	Past

Electric Power Steering (EPS)/DAST 3 (3 DTCs)

DTC	Description	Status
C1601	Battery VOLT	Past
C1608	Control unit	Past
U1000	CAN communication circuit	Past

BCM (4 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2190	Nissan anti-theft system (NATS) antenna AMP	Past

B2191	Difference of key	Past
B2193	Chain of BCM-ECM	Past

IPDM E/R (2 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
B2099	Ignition relay OFF circuit	Past

Technician Notes

2017315454

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.