

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--
VIN: MDHZBAAD0Z0518952

Odometer Reading: 162138km
License Plate: KV80DYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
Engine	 2
ABS	 6
Air bag	 6
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 3
BCM	 1
IPDM E/R	 0
Radio	 4

DTC (22)

Engine (2 DTCs)

DTC	Description	Status
P0136	Heated Oxygen Sensor (HO2S)2 (bank1)	Current
P0607	ECM	Current

ABS (6 DTCs)

DTC	Description	Status
C1130	Engine signal 1	Past
C1106	Left rear sensor 2	Past
C1109	Battery voltage (abnormal)	Past
U1002	System communication (CAN)	Past
C1115	ABS sensor (abnormal signal)	Past
C1108	Left front sensor 2	Past

Air bag (6 DTCs)

DTC	Description	Status
-----	-------------	--------

B0010:13	Assist airbag module	Current
B0001:13	Driver airbag module	Current
B1421:00	Frontal collision	Past
B1430:13	Left front pretensioner	Current
B1431:13	Right front pretensioner	Current
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (3 DTCs)

DTC	Description	Status
C1601	Battery VOLT	Past
C1608	Control unit	Past
U1000	CAN communication circuit	Past

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Radio (4 DTCs)

DTC	Description	Status
B1347	Bluetooth module 1.DEF	Current
B1342	Unit locked 1.DEF	Current
B13F0	Battery voltage 2.DEF	Past
B1328	Microphone CO	Past

Technician Notes

2017298335

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.