Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--
VIN: MDHZBAAD0Z0519647

Odometer Reading: 72612km
License Plate: CK01FRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine	0
Transmission	0
ABS	0
Air bag	1
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	1
BCM	0
IPDM E/R	0
Radio	5

DTC (7)

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1608	Control unit	Past

Radio (5 DTCs)

DTC	Description	Status
B1347	Bluetooth module 1.DEF	Current
B1342	Unit locked 1.DEF	Past
B13F0	Battery voltage 2.DEF	Past
B1324	GPS antenna circuit CO	Past

B1328	Microphone CO	Past

Technician Notes

2017327231

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.