



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250730102731
Test Time: 2025-07-30 10:27:31
Technician: Werner

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/KWID/--
VIN: MEEBBA00800843274

Odometer Reading: 10390
License Plate: LW00SCGP

Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V15.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
INJ(Injection)	 0
ABS(Anti-lock braking system)	 0
ABG(Airbag / pretensioners)	 0
TDB(Instrument panel)	 0
UCH(Central control unit)	 0
DAV(Variable power assist steering)	 0

DTC (0)

Technician Notes

2016962838

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.