**Shop Name:** –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261014104327
Test Time: 2026-10-14 10:43:27
Technician: Andrick

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/CRETA(SU2id)/--
VIN: MF3PB812LSJ146107

Odometer Reading: 15203
License Plate: MK62RLGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 14 )

| System | | Status/DTC |
|---|---|---|
| ENG (Engine) | | 0 |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) | | 1 |
| AB (Airbag) | | 1 |
| CLU (Cluster Module) | | 0 |
| IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) | | 0 |
| A/C (Air Conditioner) | | 0 |
| CODE (Transmitter Code Saving) | | 0 |
| EPS (Motor Driven Power Steering) | | 0 |
| AVN (Audio Video Navigation) | ADAS | 0 |
| IBU-BCM (Integrated Body Control Unit-Body Control Module) | | 0 |
| IBU-SMK (Integrated Body Control Unit-Smart Key Unit) | | 0 |
| IBU-IMMO (Integrated Body Control Unit-Immobilizer) | | 0 |
| ICU (Integrated Central Control Unit) | | 0 |
| RVM (Rear View Monitor) | ADAS | 0 |

## DTC ( 2 )

### ABS/ESP (Anti Lock Brake/Electronic Stability Program) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| C1102:16 | Battery voltage low | History |

## AB (Airbag) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| B1116:00 | Battery voltage unstable | History |

## Technician Notes

2017311896

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*