AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20231219111500 Test Time: 2023-12-1911:15:00

Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Avanza/--VIN: MHKM5FA2N0K006192

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V9.10

Odometer Reading: 210824 License Plate: KBF583MP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(8)

ABS ABS	⊘ 0
ABS	Q 3
	_
A/B	② 0
Combination meter	Q 2
Body	② 0
Electric power steering (EPS)	Q 3
Combination switch	② 0
IMB	② 0

▲ DTC (8)

ABS (3 DTCs)

Osmahimatian	motor (2 DTCa)	
U0100	Communication with electronic fuel injection (EFI) abnormal	Current
C1236	Abnormal cycle of FL wheel	Current
C1235	Abnormal cycle of FR wheel	Current
DTC	Description	Status

Combination meter (2 DTCs)

DTC	Description	Status
U0100	Communication with electronic fuel injection (EFI)	History
U0129	Communication with ABS/VSC	History

Electric power steering (EPS) (3 DTCs)

DTC Description Status

AUTEL www.autel.com

MaxiSys MS906 BT Page 1

Toyota/ Avanza/	Test Time: 2023-12-19 11:15:00	Report ID: MAXIA20231219111500
C1552	PIG voltage abnormality	History
U0100	CAN communication error (EFI)	History
C1557	Overheat preventive control current limit history	History

Technician Notes

2016205746

Customer name: .	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Page 2

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT