Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD **KEMPTON PARK**

Report ID: MAXIA20250430131240 Test Time: 2025-04-30 13:12:40

Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Avanza/Veloz/--VIN: MHKM5FA2N0K013298 Odometer Reading: 338572 License Plate: KMJ344MP

Customer Information

Tel: 0861033572 Name: --

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01514

Version: V11.20 Repair Order Number: --

🔁 System Scanned(8)

System	Status/DTC
EFI	② 0
ABS	Q 3
A/B	② 0
Combination meter	② 0
Body	② 0
Electric power steering (EPS)	Q 1
Combination switch	② 0
IMB	② 0

Material Description ■ DTC (4)

ABS (3 DTCs)

DTC	Description	Status
C1238	Abnormal cycle of RR wheel	Current
C1239	Abnormal cycle of RL wheel	Current
C1241	Voltage dropped/over	Current

Electric power steering (EPS) (1 DTC)

DTC	Description	Status
C1552	PIG voltage abnormality	History

Technician Notes

2016859990

www.autel.com MaxiSys MS906 BT Page 1

/Toyota/Avanza/Veloz	Test Time	2025-04-30 13:12:40	Report ID:	MAXIA20250430131240
/ TOYUTA/ AVAITZA/ VEIOZ	rest rillie.	2023-04-30 13.12.40	neport ib.	MAXIAZUZ30430131240

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



vw.autel.com MaxiSys MS906 BT Page 2