Mitsubishi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mitsubishi/XPANDER / XPANDER CROSS/--
VIN: MK2LRNC1WNN016672

Odometer Reading: 117359km
License Plate: KVH976MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
MPI/GDI/Diesel	0
AT/CVT/A-MT/TC-SST	0
ABS/ASC/EPB	0
SRS-Air Bag	1
Meter	0
4WS/Electric Power Steering	2
ETACS	0
KOS/OSS/IMMO/Keyless	0
Multi Channel Gateway	0

DTC (3)

SRS-Air Bag (1 DTC)

DTC	Description	Status
B1476	IG1(A) voltage extraordinary low	Stored DTC

4WS/Electric Power Steering (2 DTCs)

DTC	Description	Status
C1537	Ignition signal fault	Stored DTC
C1564	Vehicle speed data invalid	Stored DTC

Technician Notes

2017325982

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.