

Shop: DEKRA MFC Tel: --Email: --Address: MFC Auction House Kempton Park Report ID: MAXIA20240102114607 Test Time: 2024-01-02 11:46:07 Technician: Werner

## Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information		
/Nissan/Navara/	Odometer Reading: 278579	
VIN: MNTVCUD40Z0039802	License Plate: FVR881MP	
Customer Information		
Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE	Tel: 0861033572	
Device information		
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01482	
Version: V9.41	Repair Order Number:	

## System Scanned( 8 )

System	Status/DTC
Engine	3 1
ABS	3
Air bag	<b>o</b>
Meter/M&A	3 1
BCM	<b>o</b>
IPDM E/R	<b>o</b>
All mode AWD/4WD	3 1
Difference lock	3 1

## DTC(7) Engine(1DTC)

DTC	Description	Status		
P0502	Vehicle speed	Current		
ABS(3DTCs)				
DTC	Description	Status		
C1102	Left rear sensor 1	8 time		
C1103	Right front sensor 1	8 time		
C1104	Left front sensor 1	8 time		
Meter/M&A (1 DTC)				
DTC	Description	Status		
B2205	Vehicle speed circuit	Current		

Nissan/ Navar	ra/	Test Time: 2024-01-02 11:46:07	Report ID: MAXIA20240102114607
All mode AW	VD/4WD(1DTC)		
DTC	Description		Status
P1808	Vehicle speed SEN-ABS		Current
Difference lo	ock (1 DTC)		
DTC	Description		Status
C1203	ABS system		8 time
Technician	Notes		

2016215559

Customer name: \_\_\_\_\_

Technician:

Date:

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.