



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250612123045
Test Time: 2025-06-12 12:30:45
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/SELTOS(SP2i)/--
VIN: MZBER814MLN085967

Odometer Reading: 128145km
License Plate: JN59CMGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 4
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
ICU (Integrated Central Control Unit)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
SML (Sound Mood Lamp)	 0

DTC (5)



AB (Airbag) (4 DTCs)

DTC	Description	Status
B1101:00	Battery voltage high	History
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes
2016911156

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.