

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/SELTOS(SP2i)/--
VIN: MZBER814MMN160539

Odometer Reading: 114863km
License Plate: JY51KSGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned(15)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 2
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
ICU (Integrated Central Control Unit)	 1
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
SML (Sound Mood Lamp)	 0

 DTC (4)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

ICU (Integrated Central Control Unit) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes
2016950981

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.