

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/SONET(QY)/--
VIN: MZBFC811VPN278367

Odometer Reading: 51416
License Plate: LR05JJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
ICU (Integrated Central Control Unit)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
RVM (Rear View Monitor)	  0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
IMT (Intelligent Manual Transmission)	 0

DTC (0)

Technician Notes

2017305015

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.