



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250527102221  
Test Time: 2025-05-27 10:22:21  
Technician: Werner

# Nissan VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Nissan/Qashqai/--  
VIN: SJNFAAJ10Z2778907

Odometer Reading: 291752km  
License Plate: HPZ659FS

## Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V10.20

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 7 )

System	Status/DTC
Engine	 0
ABS	 0
Air bag	 1
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 0
BCM	 0
IPDM E/R	 0

## DTC ( 1 )

### Air bag ( 1 DTC )

DTC	Description	Status
B1129	Right side module	Past

## Technician Notes

2016891329

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

