



Shop: DEKRA MFC
 Tel: --
 Email: --
 Address: MFC Auction House
 Kempton Park

Report ID: MAXIA20240219153634
 Test Time: 2024-02-19 15:36:34
 Technician: Andrick

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Juke(2WD)/--

VIN: SJNFBAF15Z6287434

Odometer Reading: 151501

License Plate: CG28XWGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V9.50

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine	0
ABS	6
Air bag	0
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	1
BCM	2
IPDM E/R	0

DTC (9)

ABS (6 DTCs)

DTC	Description	Status
C1103	Right front sensor 1	Past
C1107	Right front sensor 2	Past
C1109	Battery voltage (abnormal)	Past
C1130	Engine signal 1	Past
C1143	Steering angle sensor circuit	Past
C1145	Yaw rate sensor	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1601	Battery VOLT	Past

BCM (2 DTCs)

DTC	Description	Status
B2193	Chain OF BCM-ECM	Past
B2196	Dongle NG	Past

Technician Notes

2016273841

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.