



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240111125354
Test Time: 2024-01-11 12:53:54
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Qashqai/--

Odometer Reading: 268910

VIN: SJNFBAJ10Z2924262

License Plate: KGZ758NW

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information








Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V9.50

Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	 2
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 2
BCM	 1
IPDM E/R	 1

DTC (6)

Engine (2 DTCs)

DTC	Description	Status
P1111	INT/V TIM V/CIR-B1	Current
P1564	ASCD SW	Current

Electric Power Steering (EPS)/DAST 3 (2 DTCs)

DTC	Description	Status
U1000	CAN COMM circuit	Past
U1200	CAN Vehicle speed ABS	Past

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	39 time

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2016225165

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.