



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250728143057
Test Time: 2025-07-28 14:30:57
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Qashqai/--
VIN: SJNFEAJ11Z2676195

Odometer Reading: 132294km
License Plate: KGK429NW

Customer Information

Name: Dekra MFC AUCTION HOUSE
















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(13)

System	Status/DTC
Engine	 1
ABS	 0
Air bag	 0
Meter/M&A	 0
Electric Power Steering (EPS)/DAST 3	 0
Air pressure monitor	 0
BCM	 1
HVAC	 0
EHS/PKB	  3
IPDM E/R	 0
CAN gateway	 0
Chassis control	  0
3-channel CAN gateway	 0

DTC (5)

Engine (1 DTC)

DTC	Description	Status
P0090:77	Fuel pressure regulator 1	Past

BCM (1 DTC)

DTC	Description	Status
B25FA:00	Rear left power window actuator	Past



EHS/PKB (3 DTCs)

DTC	Description	Status
C1BD4	G sensor (Internal electric fault)	Past
C1BD5	Power supply voltage (Battery voltage low)	Past
C1BD5	Power supply voltage (Circuit voltage out of range)	Past

Technician Notes

2016960627

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.