

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i30N(PDEN)/G 2.0 T-GDI

VIN: TMAHC51AVPJ037777

Odometer Reading: 40736KM

License Plate: MH00ZKGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V14.10

Serial Number: VB8GJCC01509

Repair Order Number: --

 System Scanned (23)

System	Status/DTC
ENG (Engine)	✓ 0
A/T (Transaxle)	✓ 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	✓ 0
AB (Airbag)	✓ 0
CLU (Cluster Module)	✓ 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	✓ 0
A/C (Air Conditioner)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
EPS (Motor Driven Power Steering)	✓ 0
ECS (Electronic Control Suspension)	✓ 0
BSD (Blind Spot Detection)	ADAS ✓ 0
SMK (Smart Key Unit)	✓ 0
PGS (Parking Guide System)	ADAS ✓ 0
DDM (Driver Door Module)	✓ 0
ADM (Assist Door Module)	✓ 0
PSM (Power Seat Module)	✓ 0
ECALL (eCall)	✓ 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	✓ 0

MFC (Multi Function Camera)		 0
WPC (Wireless Power Charger)		 0
IGPM (Integrated Gateway Power Control Module)		 0
ELSD (Electronic Limited Slip Differential)		 0
ESG (Electronic Sound Generator)		 0

 DTC (0)

Technician Notes
2017299328

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.