



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240118135955
Test Time: 2024-01-18 13:59:55
Technician: Travino

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Sportage(QLE)/--
VIN: U5YPG814MLL779241

Odometer Reading: 12197km
License Plate: n o n e n u m b e r p l a t e

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.50

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(10)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
SJB (Smart Junction Block)	 0

DTC (2)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History



Technician Notes

2016234254

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.