



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250424112527  
Test Time: 2025-04-24 11:25:27  
Technician: Andrick

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Sportage(QLE)/--  
VIN: U5YPH81AMHL396526

Odometer Reading: 140492  
License Plate: HG85SNGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.86

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 11 )

| System                                                 | Status/DTC                                                                              |
|--------------------------------------------------------|-----------------------------------------------------------------------------------------|
| ENG (Engine)                                           |  0   |
| A/T (Transaxle)                                        |  0   |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) |  0  |
| AB (Airbag)                                            |  1 |
| CLU (Cluster Module)                                   |  0 |
| A/C (Air Conditioner)                                  |  0 |
| BCM (Body Control)                                     |  0 |
| CODE (Transmitter Code Saving)                         |  0 |
| EPS (Motor Driven Power Steering)                      |  0 |
| SMK (Smart Key Unit)                                   |  0 |
| SJB (Smart Junction Block)                             |  0 |

## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

| DTC      | Description         | Status  |
|----------|---------------------|---------|
| B1102:00 | Battery voltage low | History |

## Technician Notes

201685334



Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.