



Shop: DEKRA MFC
 Tel: --
 Email: --
 Address: MFC Auction House
 Kempton Park

Report ID: MAXIA20231227143817
 Test Time: 2023-12-27 14:38:17
 Technician: Andrick

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/DUSTER/--
 VIN: VF1HJD20463044318

Odometer Reading: 118739
 License Plate: JL68VHGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE



Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V12.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(1)

System	Status/DTC
Radio 	 1

DTC (1)

Radio (1 DTC)

DTC	Description	Status
DTC934262	Unit locked Computer locked	Memory

Technician Notes

2016212429

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.