Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Yaris/--
VIN: VNKKL0D3X0A173675

Odometer Reading: 258791km
License Plate: KR21LGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine and ECT	10
ABS/VSC/TRC	1
SRS airbag	0
Combination meter	1
Main body	4
Air conditioner	1
EMPS	0
Charging control	0
Navigation system	2

DTC (19)

Engine and ECT (10 DTCs)

DTC	Description	Status
P0130	Oxygen sensor circuit (bank 1 sensor 1)	Pending
P0140	Oxygen sensor circuit no activity detected (bank 1 sensor 2)	Current
P0141	Oxygen sensor heater circuit (bank 1 sensor 2)	Pending
P1604	Startability fault	Current
P2109	Throttle/pedal position sensor A minimum stop performance	Current
P0141	Oxygen sensor heater circuit (bank 1 sensor 2)	Current
P0140	Oxygen sensor circuit no activity detected (bank 1 sensor 2)	History

P2109	Throttle/pedal position sensor A minimum stop performance	History
P0141	Oxygen sensor heater circuit (bank 1 sensor 2)	History
P1604	Startability fault	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Main body (4 DTCs)

DTC	Description	Status
B2321	Driver door motor electronic control unit(ECU) communication stop	Current
B2321	Driver door motor electronic control unit(ECU) communication stop	History
U0100	Lost communication with ECM/PCM/EV "A"	History
U0151	Lost communication with restraints control module	History

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Navigation system (2 DTCs)

DTC	Description	Status
B15B7	Bluetooth module fault	History
U0140	Lost communication with body control module (BCM)	History

Technician Notes

2017314721

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.