

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Navara/--

VIN: VSKCVND40Z0564202

Odometer Reading: 241941

License Plate: HTZ385MP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information




Scanner: MaxiSys MS906 BT

Version: V9.50

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(10)

System	Status/DTC
Engine	 1
Transmission	 1
ABS	 2
Air bag	 0
Meter/M&A	 0
BCM	 0
HVAC	 1
IPDM E/R	 0
All mode AWD/4WD	 0
Difference lock	 0

DTC (5)

Engine (1 DTC)

DTC	Description	Status
P1550	Battery current sensor	1 time

Transmission (1 DTC)

DTC	Description	Status
P1815	Manual mode switch	CRNT

ABS (2 DTCs)

DTC	Description	Status
C1163	Steering angle sensor safe	Current

C1109	Battery voltage	Current
-------	-----------------	---------

HVAC (1 DTC)

DTC	Description	Status
B2573	Battery voltage OUT OF range	Current

Technician Notes

2016240437

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.