

# BMW VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/BMW/3'/320i\_N20/--

VIN: WBA3B16030NP58161

Odometer Reading: 207712

License Plate: JW01KDGP

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Version: V20.00

Serial Number: VB8GJCC01509

Repair Order Number: --

## System Scanned( 10 )

System	Status/DTC
EKPS (Electric Fuel Pump Control)	0
EPS (Electric Power Steering)	0
FRM (Footwell Module)	0
FZD (Roof Function Center)	0
GWS (Gear Selector Switch)	0
ICM (Integrated Chassis Management)	0
IHKA (Integrated Automatic Heating And A/C System)	0
HU (Head unit)	0
CON (Controller)	0
ZGM (Central Gateway Module)	0

## DTC ( 0 )

## Technician Notes

2016285396

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.