



Shop Name: --

Tel: --

Email: --

Address: --

Report ID: MAXIA20241009132553

Test Time: 2024-10-09 13:25:53

Technician: Lebo

2018_10 BMW Vehicle Diagnostic Report

Vehicle Information

2018_10/BMW/3'/318i_B38/B38

VIN: WBA8E32030A554420

Odometer Reading: 65237km

License Plate: HW79XCGP

Customer Information

Name: --

Tel: --

Device information

Scanner: D1 ProS

Version: V14.10

Serial Number: VBBGR3C01492

Repair Order Number:
VBBGR3C0149220241009132331359

System Scanned(18)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	 0
EGS (Electronic Transmission Management)	 0
DSC (Dynamic Stability Control)	 1
ACSM (Airbag-Advanced Crash Safety Module)	 0
KOMBI (Instrument Cluster)	 0
FEM (Front Electronic Module)	 2
ZGM (Central Gateway Module)	 1
ICM (Integrated Chassis Management)	 0
EPS (Electric Power Steering)	 0
FLEL (Frontal Light Electronics Left)	 0
FLER (Frontal Light Electronics Right)	 0
FZD (Roof Function Center)	 1
GWS (Gear Selector Switch)	 0
TCB (Combox Emergency Call)	 0
HUB (Headunit Basis)	 2
CON (Controller)	 0
REM (Rear Electronic Module)	 2
IHKA (Integrated Automatic Heating And A/C System)	 0



 DTC (9)

DSC (Dynamic Stability Control) (1 DTC)

DTC	Description	Status
480A90	DSC: Roller brake tester mode active	Intermittent

FEM (Front Electronic Module) (2 DTCs)

DTC	Description	Status
8041A8	Welcome light repeat lock active	Intermittent
804415	Radio remote control: Battery undervoltage	Permanent

ZGM (Central Gateway Module) (1 DTC)

DTC	Description	Status
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent

FZD (Roof Function Center) (1 DTC)

DTC	Description	Status
801A55	DWA: The alarm has been activated	Permanent

HUB (Headunit Basis) (2 DTCs)

DTC	Description	Status
E1C602	HU-B: Ethernet: Poor signal quality	Intermittent
E1C600	HU-B: Ethernet: Unexpected communication termination	Intermittent

REM (Rear Electronic Module) (2 DTCs)

DTC	Description	Status
804872	Brake light, left, faulty	Intermittent
804890	Turn signal plausibility check failed: Function deactivated	Intermittent

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.