Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20260930120514
Test Time: 2026-09-30 12:05:14
Technician: Andrick

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Kuga/Escape/--
VIN: WF0AXXWPMAJA25127

Odometer Reading: 128535
License Plate: LL49CLGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (22)

System		Status/DTC
PCM(Powertrain control module)		2
ABS(Anti-lock brake system)		0
RCM(Restraint control module)		0
IPC(Instrument panel control module)		1
ACM(Audio control module)		0
APIM(Accessory protocol interface module)		0
BdyCM(Body control module)	ADAS	0
C-CM(Cruise control module)	ADAS	0
DDM(Driver front door module)		2
FCIM(Front controls interface module)		0
FDSM(Front distance sensing module)	ADAS	0
HCM(Headlamp control module)	ADAS	0
HVAC(Heating ventilation air conditioning)		0
IPMA(Image processing module A)	ADAS	0
PAM(Parking aid module)	ADAS	0
PDM(Passenger front door module)		2
PSCM(Power steering control module)		0
RFA(Remote function actuator)		0
RGTM(Rear gate/trunk module)		1
SASM(Steering angle sensor module)		0

SODL(Side obstacle detection control module - left)	ADAS	0
SODR(Side obstacle detection control module - right)	ADAS	0

DTC (8)

PCM(Powertrain control module) (2 DTCs)

DTC	Description	Status
P0420:00-EC	Catalyst System Efficiency Below Threshold (Bank 1)	CMDTCs
P164D:00-6C	All Wheel Drive ID Block Corrupted, Not Programmed	CMDTCs

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status
U053B:67-48	Invalid Data Received From Image Processing Module A	CMDTCs

DDM(Driver front door module) (2 DTCs)

DTC	Description	Status
U0201:87-28	Lost Communication With Door Control Module C	CMDTCs
U2013:87-28	Switch Pack	CMDTCs

PDM(Passenger front door module) (2 DTCs)

DTC	Description	Status
B12C4:15-68	Mirror Turn Indicator	CMDTCs
U0202:87-28	Lost Communication With Door Control Module D	CMDTCs

RGTM(Rear gate/trunk module) (1 DTC)

DTC	Description	Status
C2006:31-68	Left Actuator	CMDTCs

Technician Notes
2017305421

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.