

Volkswagen CV VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen CV/S6/S7 - Amarok 2017 >/--
VIN: WV1ZZZ2HZNA030546

Odometer Reading: 136844
License Plate: FVY755L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
01 - Engine Control Module 1	 1
02 - Transmission electronics	 0
03 - Brakes 1	 0
04 - Steering Angle Sender	 0
08 - Air conditioning	 0
09 - Electronic central electric	 0
10 - Parallel parking 2	 0
15 - Airbag	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Immobilizer	 0
32 - Lock Electronics	 0
5F - Information electronics 1	 1
61 - Battery Regulation	 0
65 - Tire pressure monitoring	 3
69 - Trailer Function	 3

DTC (8)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B110231	Rearview camera No signal	Passive/Sporadic

65 - Tire pressure monitoring (3 DTCs)

DTC	Description	Status
C112C00	Adaptation/part monitoring not possible Tire pressure sensor defective/no signal	Passive/Sporadic
C112B00	Adaptation not possible Too many tire pressure sensors on vehicle	Passive/Sporadic
C105131	Right front tire pressure sensor No signal	Active/static

69 - Trailer Function (3 DTCs)

DTC	Description	Status
02564:010	Bulb for left tail light on trailer - Open circuit/short circuit to B+	Active/static
02565:010	Right turn signal lamp, trailer - Open circuit/short circuit to B+	Active/static
02566:010	Left turn signal lamp, trailer - Open circuit/short circuit to B+	Active/static

Technician Notes
2017301980

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.