



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250827124817
Test Time: 2025-08-27 12:48:17
Technician: Werner

Volkswagen CV VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen CV/SH/SJ - Transporter 2019>/--
VIN: WV2ZZZ7HZMH114718

Odometer Reading: 121551
License Plate: LM48ZPGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (13)

System	Status/DTC
01 - Engine Control Module 1	2
02 - Transmission electronics	0
03 - Brakes 1	0
08 - Air Conditioning	0
09 - Electronic central electric	2
15 - Airbag	0
17 - Instrument cluster	2
19 - Gateway	1
44 - Power Steering	0
5F - Information electronics 1	1
65 - Tire pressure monitoring	0
69 - Trailer Function	0
76 - Parking assistance	0

DTC (8)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P060C00	Internal control unit main processor performance	Passive/Sporadic
P06A600	Sensor reference voltage A circuit Range/performance	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
-----	-------------	--------



B147918	Remote control key 1 Voltage too low	Active/static
B1A7529	Child safety/Safe sliding door rear front passenger side Range/Performance	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111000	Function restriction caused by communication interruption	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
U006500	Vehicle Communication Bus E Performance	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
U11B800	Interface for external media No communication	Passive/Sporadic

Technician Notes
2016992901

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.