

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/BW - Tiguan 2018 >/--
 VIN: WVGZZZ5NZLW828506

Odometer Reading: 63670km
 License Plate: JM17JYGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(24)

System	Status/DTC
01 - Engine Control Module 1	4
02 - Transmission electronics	0
03 - Brakes 1	0
08 - Air Conditioning	1
09 - Electronic central electric	0
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	0
20 - High beam assistant	0
29 - Left light control	0
36 - Seat adjustment, driver side	0
39 - Light Control Right	0
42 - Driver's door electronics	0
44 - Power Steering	0
4B - Multi-function module	0
52 - Passenger's door electronics	0
5F - Information electronics 1	1
65 - Tire pressure monitoring	0

69 - Trailer Function	✓ 0
6C - Camera System Rear View	✓ 0
76 - Parking assistance	✓ 0
CA - Sunroof control module	✓ 0
D6 - Light Control Left 2	✓ 0
D7 - Light Control Right 2	✓ 0

DTC (6)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030400	Cylinder 4 Misfire detected	Passive/Sporadic
P036300	Misfire detected - fueling disabled	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B105113	Telephone baseplate Open circuit	Active/static

Technician Notes

2016205000

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.