



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250414152537
Test Time: 2025-04-14 15:25:37
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/16 - Jetta 2011 >/--
VIN: WVWZZZ16ZEM052850

Odometer Reading: 186902
License Plate: DG25HHGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System	Status/DTC
01 - Engine Control Module 1	 0
02 - Transmission electronics	 0
03 - Brakes 1	 2
08 - Air Conditioning	 0
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
42 - Driver's door electronics	 1
44 - Power Steering	 0
52 - Passenger's door electronics	 0
56 - Radio	 0
69 - Trailer Function	 0
77 - Telephone	 0

DTC (3)

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
03543:000	Mechanical malfunction in suspension	Passive/Sporadic
02214:002	Tire pressure warning - Lower limit not reached	Active/static



42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B11EC54	Motor for front window regulator No basic setting	Passive/Sporadic

Technician Notes

2016842818

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.