

Shop Name: Dekra MFC Auction House

Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD **KEMPTON PARK** 

Report ID: MAXIA20250729120609 Test Time: 2025-07-29 12:06:09

Technician: Werner

# Volkswagen VEHICLE DIAGNOSTIC REPORT

#### **Vehicle Information**

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--VIN: WVWZZZ60ZKT096366

License Plate: JZ71XJGP

Odometer Reading: 145638

**Customer Information** 

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

**Device information** 

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V22.50

Repair Order Number: --

### 🔁 System Scanned( 12 )

System	Status/DTC
01 - Engine Control Module 1	<b>②</b> 0
03 - Brakes 1	<b>②</b> 0
04 - Steering Angle Sender	<b>②</b> 0
09 - Electronic central electric	<b>Q</b> 2
15 - Airbag	<b>②</b> 0
17 - Instrument cluster	<b>②</b> 0
19 - Gateway	<b>Q</b> 1
25 - Anti-Theft Immobilizer	<b>Q</b> 1
44 - Power Steering	<b>②</b> 0
55 - Headlight Regulation	<b>②</b> 0
56 - Radio	<b>Q</b> 4
61 - Battery Regulation	<b>②</b> 0

## Material Description ■ DTC (8)

### 09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
03156:004	Anti-theft alarm system sensor - No signal/communication	Active/static
10 Cotower (1 DTC)		

### 19 - Gateway (1 DTC)

Description **Status** 

MaxiSys MS906 BT

/Volkswagen/60/	61/64 - Polo/Vento 2010 > Tes	et Time: 2025-07-29 12:00	6:09 Report ID: MAXIA20250729120609
01044:000	Control module incorrectly co	Passive/Sporadic	
25 - Anti-Theft	Immobilizer (1 DTC)		
DTC	Description		Status
B104A00	Engine control unit 1/power el	orized Passive/Sporadic	
56 - Radio ( 4 [	OTCs)		
DTC	Description		Status
00870:011	Left front bass speaker - Open circuit		Active/static
00871:011	Right front bass speaker - Ope	Active/static	
00872:011	Left rear bass speaker - Open	Active/static	
00873:011	Right rear bass speaker - Ope	n circuit	Active/static
Technician No 2016961407	otes		
		Customer name:	

Technician:

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com MaxiSys MS906 BT Page 2