Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: WVWZZZ60ZMT119482

Odometer Reading: 365265
License Plate: KR48KLGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	0
09 - Electronic central electric	2
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	2
44 - Power steering	3
56 - Radio	5

DTC (14)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1570:00/05 488:000	Engine control unit disabled	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

44 - Power steering (3 DTCs)

DTC	Description	Status
U140A00	Terminal 30 ,Open circuit	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
P332500	Voltage supply Kl.15 ,implausible	Passive/Sporadic

56 - Radio (5 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00870:011	Left front bass speaker - Open circuit	Active/static
00871:011	Right front bass speaker - Open circuit	Active/static
00872:011	Left rear bass speaker - Open circuit	Active/static
00873:011	Right rear bass speaker - Open circuit	Active/static

Technician Notes

2017316731

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.