Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >/--
VIN: WVWZZZAUZKW103130

Odometer Reading: 206899km
License Plate: JD92NDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (19)

System	Status/DTC
01 - Engine Control Module 1	6
02 - Transmission electronics	0
03 - Brakes 1	0
08 - Air conditioning	0
09 - Electronic central electric	0
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	4
20 - High beam assistant	1
29 - Left light control	0
39 - Light Control Right	0
42 - Driver's door electronics	0
44 - Power steering	0
4B - Multi-function module	0
52 - Passenger's door electronics	0
5F - Information electronics 1	2
A9 - Structure-Borne Sound Actuator	0
D6 - Light control left 2	0
D7 - Light control right 2	0

DTC (13)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
P006800	MAP/MAF - Throttle Position ,Correlation	Passive/Sporadic
P227900	Intake air system leakage	Passive/Sporadic
P001700	Camshaft position 2/crankshaft position sensor (bank 1) , Incorrect allocation	Passive/Sporadic
P001600	Crankshaft Position (CKP)-Camshaft Position (CMP) , Correlation (bank 1 sensor A)	Active/static
P034100	Camshaft Position Sensor ,Implausible signal	Passive/Sporadic
U044700	Invalid data received from serial data gateway module A	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U112400	Data bus ,Additional installations detected	Active/static
P1B0000	Generator mechanical fault	Passive/Sporadic
P1B0100	Generator ,Electrical fault	Passive/Sporadic
U140600	Static current ,too high	Passive/Sporadic

20 - High beam assistant (1 DTC)

DTC	Description	Status
U101300	Control module not coded	Active/static

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
B106713	Right rear bass speaker ,Open circuit	Active/static
B106213	Right front bass speaker ,Open circuit	Active/static

Technician Notes

2017313846

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.