



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	08/09/2026		M57 Pretoria Road - 1619
Inspection Date	08/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	LCN438NW
Model	STARLET CROSS 1.5 XR AT [2024-ON]	Register Number	
VIN	JTDLWFA3S00284814	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2026
Color	RED	Power / Displacement	
Year Model	2024	Paint Finish	M - METALLIC
Km Reading	48,109 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:

2017295712

DATE

08/09/2026

Damage

Repair Way

Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.3	2.4	-	
Rear	1.5	1.8	-	
Emergency / Parking	1.1	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R16	89H	Goodyear	Assurance	V	1824	3 mm
Front Right	195/60R16	89H	Goodyear	Assurance	V	1724	3 mm
Rear Left	195/60R16	89H	Goodyear	Assurance	V	1824	3 mm
Rear Right	195/60R16	89H	Goodyear	Assurance	V	1624	3 mm
Spare	195/60R16	89H	Goodyear	Assurance	V	1824	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1157-1C	POWER SUPPLY VOLTAGE ABNORMAL	HISTORY

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:


2017295712

DATE

08/09/2026



LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026



90 DEGREE REAR



90 DEGREE RIGHT



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026



ENGINE 1



Oil cap and dipstick



Coolant bottle



ENGINE 2



CHASSIS



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT




Report No:

2017295712

DATE _____

08/09/2026



LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD

Yuma Co. Street: City, state, zip: Telephone: Telex: Fax: Test date: 12-31 Test results:		Car License pl. no.: Mileage: Make: Manufacturer: Model: VIN: J10-4FA300010114		1/10/2002 01200 KIA NISSAN 2001	1/10/2002 01200 KIA NISSAN 2001
Test auto: 1-4 miles Stock number: 100100000		Test auto: 10-15 miles Stock number: 100100000		1-4 miles 10-15 miles 16-20 miles 21-25 miles 26-30 miles 31-35 miles 36-40 miles 41-45 miles 46-50 miles 51-55 miles 56-60 miles 61-65 miles 66-70 miles 71-75 miles 76-80 miles 81-85 miles 86-90 miles 91-95 miles 96-100 miles 101-105 miles 106-110 miles 111-115 miles 116-120 miles 121-125 miles 126-130 miles 131-135 miles 136-140 miles 141-145 miles 146-150 miles 151-155 miles 156-160 miles 161-165 miles 166-170 miles 171-175 miles 176-180 miles 181-185 miles 186-190 miles 191-195 miles 196-200 miles 201-205 miles 206-210 miles 211-215 miles 216-220 miles 221-225 miles 226-230 miles 231-235 miles 236-240 miles 241-245 miles 246-250 miles 251-255 miles 256-260 miles 261-265 miles 266-270 miles 271-275 miles 276-280 miles 281-285 miles 286-290 miles 291-295 miles 296-300 miles 301-305 miles 306-310 miles 311-315 miles 316-320 miles 321-325 miles 326-330 miles 331-335 miles 336-340 miles 341-345 miles 346-350 miles 351-355 miles 356-360 miles 361-365 miles 366-370 miles 371-375 miles 376-380 miles 381-385 miles 386-390 miles 391-395 miles 396-400 miles 401-405 miles 406-410 miles 411-415 miles 416-420 miles 421-425 miles 426-430 miles 431-435 miles 436-440 miles 441-445 miles 446-450 miles 451-455 miles 456-460 miles 461-465 miles 466-470 miles 471-475 miles 476-480 miles 481-485 miles 486-490 miles 491-495 miles 496-500 miles 501-505 miles 506-510 miles 511-515 miles 516-520 miles 521-525 miles 526-530 miles 531-535 miles 536-540 miles 541-545 miles 546-550 miles 551-555 miles 556-560 miles 561-565 miles 566-570 miles 571-575 miles 576-580 miles 581-585 miles 586-590 miles 591-595 miles 596-600 miles 601-605 miles 606-610 miles 611-615 miles 616-620 miles 621-625 miles 626-630 miles 631-635 miles 636-640 miles 641-645 miles 646-450 miles 651-655 miles 656-660 miles 661-665 miles 666-670 miles 671-675 miles 676-680 miles 681-685 miles 686-690 miles 691-695 miles 696-700 miles 701-705 miles 706-710 miles 711-715 miles 716-720 miles 721-725 miles 726-730 miles 731-735 miles 736-740 miles 741-745 miles 746-750 miles 751-755 miles 756-760 miles 761-765 miles 766-770 miles 771-775 miles 776-780 miles 781-785 miles 786-790 miles 791-795 miles 796-800 miles 801-805 miles 806-810 miles 811-815 miles 816-820 miles 821-825 miles 826-830 miles 831-835 miles 836-840 miles 841-845 miles 846-850 miles 851-855 miles 856-860 miles 861-865 miles 866-870 miles 871-875 miles 876-880 miles 881-885 miles 886-890 miles 891-895 miles 896-900 miles 901-905 miles 906-910 miles 911-915 miles 916-920 miles 921-925 miles 926-930 miles 931-935 miles 936-940 miles 941-945 miles 946-950 miles 951-955 miles 956-960 miles 961-965 miles 966-970 miles 971-975 miles 976-980 miles 981-985 miles 986-990 miles 991-995 miles 996-1000 miles	
Test auto: 1-4 miles Stock number: 100100000		Test auto: 10-15 miles Stock number: 100100000		1-4 miles 10-15 miles 16-20 miles 21-25 miles 26-30 miles 31-35 miles 36-40 miles 41-45 miles 46-50 miles 51-55 miles 56-60 miles 61-65 miles 66-70 miles 71-75 miles 76-80 miles 81-85 miles 86-90 miles 91-95 miles 96-100 miles 101-105 miles 106-110 miles 111-115 miles 116-120 miles 121-125 miles 126-130 miles 131-135 miles 136-140 miles 141-145 miles 146-150 miles 151-155 miles 156-160 miles 161-165 miles 166-170 miles 171-175 miles 176-180 miles 181-185 miles 186-190 miles 191-195 miles 196-200 miles 201-205 miles 206-210 miles 211-215 miles 216-220 miles 221-225 miles 226-230 miles 231-235 miles 236-240 miles 241-245 miles 246-250 miles 251-255 miles 256-260 miles 261-265 miles 266-270 miles 271-275 miles 276-280 miles 281-285 miles 286-290 miles 291-295 miles 296-300 miles 301-305 miles 306-310 miles 311-315 miles 316-320 miles 321-325 miles 326-330 miles 331-335 miles 336-340 miles 341-345 miles 346-350 miles 351-355 miles 356-360 miles 361-365 miles 366-370 miles 371-375 miles 376-380 miles 381-385 miles 386-390 miles 391-395 miles 396-400 miles 401-405 miles 406-410 miles 411-415 miles 416-420 miles 421-425 miles 426-430 miles 431-435 miles 436-440 miles 441-445 miles 446-450 miles 451-455 miles 456-460 miles 461-465 miles 466-470 miles 471-475 miles 476-480 miles 481-485 miles 486-490 miles 491-495 miles 496-500 miles 501-505 miles 506-510 miles 511-515 miles 516-520 miles 521-525 miles 526-530 miles 531-535 miles 536-540 miles 541-545 miles 546-450 miles 551-555 miles 556-560 miles 561-565 miles 566-570 miles 571-575 miles 576-580 miles 581-585 miles 586-590 miles 591-595 miles 596-600 miles 601-605 miles 606-610 miles 611-615 miles 616-620 miles 621-625 miles 626-630 miles 631-635 miles 636-640 miles 641-645 miles 646-450 miles 651-655 miles 656-660 miles 661-665 miles 666-670 miles 671-675 miles 676-680 miles 681-685 miles 686-690 miles 691-695 miles 696-700 miles 701-705 miles 706-710 miles 711-715 miles 716-720 miles 721-725 miles 726-730 miles 731-735 miles 736-740 miles 741-745 miles 746-750 miles 751-755 miles 756-760 miles 761-765 miles 766-770 miles 771-775 miles 776-780 miles 781-785 miles 786-790 miles 791-795 miles 796-800 miles 801-805 miles 806-810 miles 811-815 miles 816-820 miles 821-825 miles 826-830 miles 831-835 miles 836-840 miles 841-845 miles 846-850 miles 851-855 miles 856-860 miles 861-865 miles 866-870 miles 871-875 miles 876-880 miles 881-885 miles 886-890 miles 891-895 miles 896-900 miles 901-905 miles 906-910 miles 911-915 miles 916-920 miles 921-925 miles 926-930 miles 931-935 miles 936-940 miles 941-945 miles 946-950 miles 951-955 miles 956-960 miles 961-965 miles 966-970 miles 971-975 miles 976-980 miles 981-985 miles 986-990 miles 991-995 miles 996-1000 miles	

Shock and brake report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:

2017295712

DATE

08/09/2026



Diagnostic report



Water level



Bonnet



Windscreen



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026



Side Mirror Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: JTDLWFA3S00284814



CONDITION REPORT



Report No:
2017295712
DATE
08/09/2026



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDLWFA3S00284814