

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	17/04/2024		M57 Pretoria Road - 1619
Inspection Date	17/04/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	KIA	Registration Number	JD01VPGP
Model	PICANTO	Register Number	
VIN	KNAB3512MKT515955	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2021
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	48,844 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Tyre Front Right Torn / Cut	Repair
Tyre Rear Left Torn / Cut	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
L/F fog light trimming missing	Replace

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.6	2.8	-	
Rear	1.7	1.9	-	
Emergency / Parking	1.2	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/55R15	86H	Kumho	Ecowing	V	1419	3 mm
Front Right	185/55R15	82H	Kumho	Ecowing	V	2717	3 mm
Rear Left	185/55R15	86H	Kumho	Ecowing	V	1819	3 mm
Rear Right	185/55R15	86H	Kumho	Ecowing	V	1319	3 mm
Spare	T115/70D15	90M	Maxxis	Temporary	V	////	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

Vehicle Data				Mileage			
Make/Model	Year	Colour	Engine	Current	Previous	Unit	Notes
Toyota Aygo	2018	White	1.0L	10,000	0	km	
Registration	Test Date	Test Mileage	Test Result	Test Mileage	Test Result	Test Result	Test Result
SA 1234567	15/04/24	10,000	Pass	0	Pass	Pass	Pass
Shock and Brake Report							
Shock absorber	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake pads	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake discs	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake lines	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake master cylinder	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake booster	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake pedal	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake fluid	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brake system	Worn	Worn	Worn	Worn	Worn	Worn	Worn

Shock and brake report

Vehicle Data				Mileage			
Make/Model	Year	Colour	Engine	Current	Previous	Unit	Notes
Toyota Aygo	2018	White	1.0L	10,000	0	km	
Registration	Test Date	Test Mileage	Test Result	Test Mileage	Test Result	Test Result	Test Result
SA 1234567	15/04/24	10,000	Pass	0	Pass	Pass	Pass
Diagnostic Report							
Engine	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Transmission	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Drivetrain	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Steering	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Suspension	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brakes	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Wheels	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Tires	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Exhaust	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Electrical	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Interior	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Exterior	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Body	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Paint	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Windows	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Doors	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Lights	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Wipers	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Climate	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Audio	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Navigation	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Telematics	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Security	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Insurance	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Registration	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Tax	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Motoring	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Driving	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Accidents	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Repairs	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Modifications	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Ownership	Worn	Worn	Worn	Worn	Worn	Worn	Worn
History	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Value	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Resale	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Lease	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Finance	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Insurance	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Registration	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Tax	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Motoring	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Driving	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Accidents	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Repairs	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Modifications	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Ownership	Worn	Worn	Worn	Worn	Worn	Worn	Worn
History	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Value	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Resale	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Lease	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Finance	Worn	Worn	Worn	Worn	Worn	Worn	Worn

Diagnostic report

Vehicle Data				Mileage			
Make/Model	Year	Colour	Engine	Current	Previous	Unit	Notes
Toyota Aygo	2018	White	1.0L	10,000	0	km	
Registration	Test Date	Test Mileage	Test Result	Test Mileage	Test Result	Test Result	Test Result
SA 1234567	15/04/24	10,000	Pass	0	Pass	Pass	Pass
Diagnostic Report							
Engine	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Transmission	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Drivetrain	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Steering	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Suspension	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Brakes	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Wheels	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Tires	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Exhaust	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Electrical	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Interior	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Exterior	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Body	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Paint	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Windows	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Doors	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Lights	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Wipers	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Climate	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Audio	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Navigation	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Telematics	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Security	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Insurance	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Registration	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Tax	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Motoring	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Driving	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Accidents	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Repairs	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Modifications	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Ownership	Worn	Worn	Worn	Worn	Worn	Worn	Worn
History	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Value	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Resale	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Lease	Worn	Worn	Worn	Worn	Worn	Worn	Worn
Finance	Worn	Worn	Worn	Worn	Worn	Worn	Worn

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016344858

VIN: KNAB3512MKT515955

DATE

17/04/2024



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

VIN: KNAB3512MKT515955

6 / 8



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD




RF TYRE TREAD



Spare wheel

VIN: KNAB3512MKT515955

7 / 8





Oil cap and dipstick



Water level



Bonnet



Front Bumper



Front Bumper



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Tyre Front Right



Tyre Rear Left



CONDITION REPORT

Report No: 2016344858

DATE
17/04/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za