



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/06/2025		M57 Pretoria Road - 1619
Inspection Date	11/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	GWM	Registration Number	KY40KMGP
Model	P-SERIES 2.0TD CV DLX DSL D-CAB PU 8-SP AT [2020-2025]	Register Number	
		Date Of First Licensing	
VIN	LGWCBF198NJ630882	Last COR	
Engine Number		License Expiry Date	31/12/2025
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	M - METALLIC
Year Model	2023	Fuel	DIESEL
Km Reading	93,785 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025

	Damage	Repair Way
	Tail Light Left Damaged	Replace
	Tail Light Right Damaged	Replace
	Front Bumper Paintwork • Scratched	Repair
	Front Fender Right Dented	Repair
	Rear Fender Left Dented	Repair
	Rear Fender Right Dented	Repair
	Door Front Left Dented	Repair
	Door Front Right Paintwork • Scratched	Repair
	Door Rear Left Paintwork • Scratched	Repair
	Door Rear Right Dented	Repair
	Tailgate Dented	Repair
	Rear bumper Dented	Repair
	Windscreen Chipped	Repair
	Parking Brake Performance Left / Right Difference out of legal range	Repair

Brakes
Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.9	4.9	-	
Rear	2.5	2.5	-	
Emergency / Parking	0.6	0.1	-	

Tyres and Rims
Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/70R17	110T	Chao yang	Su318	V	2422	3 mm
Front Right	245/70R17	110T	Chao yang	Su318	V	2422	3 mm
Rear Left	245/70R17	110T	Chao yang	Su318	V	2522	4 mm
Rear Right	245/70R17	110T	Chao yang	Su318	V	2422	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT DTC	B185100	IGNITION KEY BATTERY LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025

[illegible]

Shock and brake report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



90 DEGREE REAR




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



No spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



Coolant bottle



Oil cap and dipstick



Water level



Windscreen

[illegible]

Parking Brake Performance



Front Bumper

DEKRA Automotive (PTY) Ltd
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



Front Bumper



Front Fender Right



Rear Fender Right



Door Rear Right



Door Front Right



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: LGWCBF198NJ630882



CONDITION REPORT



Report No:
2016909727
DATE
11/06/2025



Door Rear Left



Rear Fender Left



Tailgate



Rear bumper



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWCBF198NJ630882