



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/09/2026		M57 Pretoria Road - 1619
Inspection Date	25/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	CHERY	Registration Number	LCJ399NW
Model	TIGGO 7 PRO 1.5T EXECUTIVE CVT [2022-2025]	Register Number	
		Date Of First Licensing	
VIN	LVVDB21B2RD767285	Last COR	
Engine Number		License Expiry Date	31/08/2027
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2024	Fuel	PETROL
Km Reading	34,273 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Bonnet Dented	Repair
Rear Fender Left Paintwork • Chipmarks	Repair
Windscreen Cracked	Replace
Tyre Rear Left Worn	Replace
Gearbox Oil Leak	Repair
Deceleration parking brake defective	Repair
Warning light illuminated on dashboard	Repair



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.38	3.28	-	
Rear	3.03	2.73	-	
Emergency / Parking	0.44	0.77	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/60 R18	100H	Citi	Comfort	V	1924	1 mm
Front Right	225/60 R18	100H	Citi	Comfort	V	1924	2 mm
Rear Left	225/60 R18	100H	Citi	Comfort	V	1924	0 mm
Rear Right	225/60 R18	100H	Citi	Comfort	V	1924	2 mm
Spare	225/60 R18	100H	Citi	Comfort	V	1324	7 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	TIRE PRESSURE MONITORING SYSTEM(TPMS)	U010187	CAN COMMUNICATION ERROR-LOST COMMUNICATION WITH TR	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:

2017302439

DATE

25/09/2026

Client Information				Vehicle Information			
Client Name	Mr. M. M. M.	Client Address	123 Main St, Pretoria	Vehicle Make	Toyota	Vehicle Model	Proace
Client Phone	012 345 6789	Client Email	m.m.m@example.co.za	Vehicle Year	2018	Vehicle Mileage	150,000 km
Technician	J. J. J.	Technician License	123456789	Vehicle VIN	12345678901234567890		
Inspection Results				Brake and Shock Absorber Report			
Front Left	Good	Front Right	Good	Shock Absorber	Good	Brake Pads	Good
Rear Left	Good	Rear Right	Good	Shock Absorber	Good	Brake Pads	Good
Front Left	Good	Front Right	Good	Shock Absorber	Good	Brake Pads	Good
Rear Left	Good	Rear Right	Good	Shock Absorber	Good	Brake Pads	Good

Brake and shock absorber report

Diagnostic Report Page 1			
Engine	Good	Transmission	Good
Brake	Good	Steering	Good
Wipers	Good	Windows	Good
Seats	Good	Interior	Good
Exterior	Good	Paint	Good
Wheels	Good	Tires	Good
Fluids	Good	Oil	Good
Filters	Good	Spark Plugs	Good
Belts	Good	Hoses	Good
Washers	Good	Waxes	Good
Tools	Good	Accessories	Good
Other	Good	Notes	Good

Diagnostic report page 1

Diagnostic Report Page 2			
Engine	Good	Transmission	Good
Brake	Good	Steering	Good
Wipers	Good	Windows	Good
Seats	Good	Interior	Good
Exterior	Good	Paint	Good
Wheels	Good	Tires	Good
Fluids	Good	Oil	Good
Filters	Good	Spark Plugs	Good
Belts	Good	Hoses	Good
Washers	Good	Waxes	Good
Tools	Good	Accessories	Good
Other	Good	Notes	Good

Diagnostic report page 2

Diagnostic Report Page 3			
Engine	Good	Transmission	Good
Brake	Good	Steering	Good
Wipers	Good	Windows	Good
Seats	Good	Interior	Good
Exterior	Good	Paint	Good
Wheels	Good	Tires	Good
Fluids	Good	Oil	Good
Filters	Good	Spark Plugs	Good
Belts	Good	Hoses	Good
Washers	Good	Waxes	Good
Tools	Good	Accessories	Good
Other	Good	Notes	Good

Diagnostic report page 3

Diagnostic Report Page 4			
Engine	Good	Transmission	Good
Brake	Good	Steering	Good
Wipers	Good	Windows	Good
Seats	Good	Interior	Good
Exterior	Good	Paint	Good
Wheels	Good	Tires	Good
Fluids	Good	Oil	Good
Filters	Good	Spark Plugs	Good
Belts	Good	Hoses	Good
Washers	Good	Waxes	Good
Tools	Good	Accessories	Good
Other	Good	Notes	Good

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026



RF TYRE TREAD



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026



Rear chassis



Oil cap and dipstick



Windscreen



Bonnet



Water level



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285



CONDITION REPORT



Report No:
2017302439
DATE
25/09/2026



Gearbox



Tyre Rear Left



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LVVDB21B2RD767285