



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/01/2024		M57 Pretoria Road - 1619
Inspection Date	09/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	LD65CZGP
Model	CELERIO	Register Number	
VIN	MA3KFC42S00439959	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2024
Color	GREY	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	137,146 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Air cleaner Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Flaking	Repair
Sill Panel Right Dented	Repair
Windscreen Chipped	Repair
Tyre Front Left Smooth	Replace
Tyre Front Right Smooth	Replace
Spare Tyre Damaged	Repair
Main Beam Right Dented	Repair
Silencer Missing	Replace
Radiator Cradle Dented	Repair
Tire is damage in boot can't see details	Replace
R/F fender line missing	Replace
L/F fender line damage	Replace



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Brakes

Brake Test Results

	Left	Right		
	Braking Force [kN]	Braking Force [kN]	Axle Weight [kg]	Deceleration [m/s ²]
Front	1.4	1.6	-	
Rear	1.5	1.3	-	
Emergency / Parking	1	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Kumho	Sense	V	5019	0 mm
Front Right	175/70R14	84H	Bridgestone	B391	V	4405	0 mm
Rear Left	165/80R13	83T	Regal	Rst-300	V	2913	2 mm
Rear Right	175/70R14	84T	Goodride	Radial	V	3620	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Body • Exterior: Vehicle got minor scratches, stone chips and dents on some body panels. flaking on some body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

VIN: MAF1N61200022832

Report No: 200022832

2 / 12

DATE

09/01/2024

Shock and brake report

Diagnostic report

Diagnostic report





CONDITION REPORT

Report No: 2016221832

VIN: MA3KFC42S00439959

DATE

09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE

VIN: MA3KFC4290132024

4 / 12



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN: MA3KFC42S00439959

5 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN: MA3KFC42S00439959

6 / 12



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel fitted



LICENSE DISC



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN: MA3KFC42S00439959

7 / 12



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN PLATE OR STICKER

VIN: MA3KFC42S00439959
8 / 12

ENGINE 1



ENGINE 2



CHASSIS



Manual



Coolant bottle



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN: MA3KFC42S00439959

9 / 12



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Oil cap and dipstick



Center Console / Cubbyhole + Lid



Windscreen



Water level



Air cleaner



Spare Tyre



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

VIN: MA3KFC42S00439959

11 / 12



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Bonnet



Side Mirror Right



Side Mirror Right



Side Mirror Left



Door Front Right



Front Bumper



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Front Bumper



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Rear bumper



Boot Lid / Hatch door



Sill Panel Right



Door Rear Right



Radiator Cradle



Radiator Cradle



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

Silencer



Silencer



Tyre Front Left



Tyre Front Right



Main Beam Right



CONDITION REPORT

Report No: 2016221832

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za