



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/04/2025		M57 Pretoria Road - 1619
Inspection Date	30/04/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	FORD	Registration Number	JT90LXGP
Model	ECOSPORT	Register Number	
VIN	MAJAXXMRKAHA81604	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	232,374 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Seat Front Right Torn / Cut	Repair
Door Panel Front Right Torn / Cut	Repair
Rear Fender Left Dented	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Tyre Front Left Excessive Wear & Tear	Replace
Tyre Front Right Torn / Cut	Replace
Gearbox Mountings Cracked	Replace
No sparewheel	Replace
Body panels	Signs of spray work done on some body panels
Body panels	Minor dents scratches stone chips on some body pan

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.9	3.2	-	
Rear	1.9	1.7	-	
Emergency / Parking	1.4	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Lanvigator	Comfort	V	0422	1 mm
Front Right	195/55R16	87H	Continental	Control	V	1519	1 mm
Rear Left	205/60R16	92H	Giti	Comfort	V	0919	1 mm
Rear Right	205/60R16	92H	Goodyear	Assurance	V	3714	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	POWERTRAIN CONTROL MODULE	P0420:09-68	CATALYST SYSTEM EFFICIENCY BELOW THRESHOLD	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025



Manual



Sparewheel covered




Expansion bottle



Oil cap and dipstick



Rear end



Shock and brake report


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604




CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

Diagnostic test



Diagnostic test results



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAH81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

CHASSIS



ENGINE 2



Seat Front Right



Door Panel Front Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

Tail Light Right



Tail Light Left



Boot Lid / Hatch door



Rear Fender Left



Windscreen



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604



CONDITION REPORT

Report No: 2016859733

DATE
30/04/2025

Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Engine



Gearbox Mountings



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604

**CONDITION REPORT**

Report No: 2016859733

DATE
30/04/2025

Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAHA81604