



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	LBP995MP
Model	I 10	Register Number	
VIN	MALB251ALRM496535	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2026
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	34,681 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:

2017305030

DATE

29/09/2026

Damage

Repair Way

Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Boot not opening can not see spare wheel	Repair
Foreign substance on oil cap	Repair



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.6	1.6	-	
Rear	1.5	1.6	-	
Emergency / Parking	1.2	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Goodyear	Assurance	V	3823	3 mm
Front Right	165/70R14	81T	Goodyear	Assurance	V	3623	3 mm
Rear Left	165/70R14	81T	Goodyear	Assurance	V	3723	3 mm
Rear Right	165/70R14	81T	Goodyear	Assurance	V	3723	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:

2017305030

DATE

29/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Rain at time of inspection

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:

2017305030

DATE _____

29/09/2026

 MAHA MOTORHOLDING 9-7-86-101																			
Name/Cn. Horse City/club/ally Trainers Trn. desc. Trn. desc. Cnt 2000/07/20 15.51	Grmns gl. no. Midge Ind. reg. Show features YPR L100/01 (P 3.011 Ind. reg. 3/20/01 11/10/01	Car L100/01 (P 3.011 Ind. reg. 3/20/01 11/10/01 MAHA/01/11/10/01/01	L100/01 3.011 11/10/01		Results 11/10/01														
Total results 11/10/01																			
side/side type 11/10/01																			
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01										Head size - 8 inch 11/10/01									
Head size - 8 inch 11/10/01																			

Shock and brake report

[illegible]

Diagnostic report

[illegible]

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026



VIN PLATE OR STICKER



ENGINE 1



CHASSIS



ENGINE 2



Coolant bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026



Water level



Rear Fender Right



Front Bumper



Front Bumper



Bonnet



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALB251ALRM496535



CONDITION REPORT



Report No:
2017305030
DATE
29/09/2026



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM496535