



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/09/2026		M57 Pretoria Road - 1619
Inspection Date	25/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	RENAULT	Registration Number	MD16VFGP
Model	KWID	Register Number	
VIN	MEEBBA00100861101	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	107,815 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Fan Belt Torn / Cut	Replace
Air cleaner Damaged	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Parcel Tray Missing	Replace
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Roof Dented	Repair
Windscreen Cracked	Repair
Tyre Rear Left Smooth	Replace
Rim Rear Left Deformed	Replace
Radiator Cross Member Damaged	Repair
Hail damaged on body panels	Repair
Body exterior	Residual traces of poor repair on body panels
Body exterior	Signs of spray work done on body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.0	2.3	-	
Rear	1.0	0.9	-	
Emergency / Parking	0.7	0.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Ceat	Fuelsmart	V	3024	3 mm
Front Right	165/70R14	81T	Ceat	Fuelsmart	V	3824	3 mm
Rear Left	165/70R14	81T	Ceat	Fuelsmart	V	3024	0 mm
Rear Right	165/70R14	81T	Ceat	Fuelsmart	V	3024	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC030166	MISFIRE ON CYLINDER 1 DESTRUCTIVE MISFIRING	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:

2017303373

DATE

25/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



LR TYRE TREAD



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:


2017303373

DATE

25/09/2026



RR TYRE TREAD



RF TYRE TREAD



No sparewheel



Coolant reservoir



Dipstick



Oil cap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



REAR



ENGINE 1



ENGINE 2



CHASSIS



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026

Car				Car			
Name/Co:				License plate no:			
Model:				Make:			
Type/Make/Model:				Year/Make/Model:			
Test date:				Test location:			
Test results:				Remarks:			
Side-slip test				Steering wheel test			
Front axle: + 3.00 mm				Rear axle: + 4.00 mm			
Shock absorber test (HDS/ABS)				Brake test			
Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00				Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00			
Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00				Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00			
Total weight: 0.00				Total weight: 0.00			

SHOCK REPORT

Car		Car	
Name/Co:		License plate no:	
Model:		Make:	
Type/Make/Model:		Year/Make/Model:	
Test date:		Test location:	
Test results:		Remarks:	
Side-slip test		Steering wheel test	
Front axle: + 3.00 mm		Rear axle: + 4.00 mm	
Shock absorber test (HDS/ABS)		Brake test	
Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Total weight: 0.00		Total weight: 0.00	

DIAGNOSTIC REPORT PAGE 1

Car		Car	
Name/Co:		License plate no:	
Model:		Make:	
Type/Make/Model:		Year/Make/Model:	
Test date:		Test location:	
Test results:		Remarks:	
Side-slip test		Steering wheel test	
Front axle: + 3.00 mm		Rear axle: + 4.00 mm	
Shock absorber test (HDS/ABS)		Brake test	
Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Total weight: 0.00		Total weight: 0.00	


DIAGNOSTIC REPORT PAGE 2

Car		Car	
Name/Co:		License plate no:	
Model:		Make:	
Type/Make/Model:		Year/Make/Model:	
Test date:		Test location:	
Test results:		Remarks:	
Side-slip test		Steering wheel test	
Front axle: + 3.00 mm		Rear axle: + 4.00 mm	
Shock absorber test (HDS/ABS)		Brake test	
Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Total weight: 0.00		Total weight: 0.00	

DIAGNOSTIC REPORT PAGE 3

Car		Car	
Name/Co:		License plate no:	
Model:		Make:	
Type/Make/Model:		Year/Make/Model:	
Test date:		Test location:	
Test results:		Remarks:	
Side-slip test		Steering wheel test	
Front axle: + 3.00 mm		Rear axle: + 4.00 mm	
Shock absorber test (HDS/ABS)		Brake test	
Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Front axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00		Rear axle: left: 0.00, right: 0.00, Difference: 0.00, Weight: 0.00	
Total weight: 0.00		Total weight: 0.00	

DIAGNOSTIC REPORT PAGE 4



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



Roof



Roof



Roof



Front Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:

2017303373

DATE

25/09/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



Parcel Tray



Boot Lid / Hatch door



Front Fender Left

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



Bonnet



Engine Wiring



Air cleaner



Headlight Left



Headlight Right



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



Engine Wiring



Bonnet



Front Bumper



Front Bumper



Front Bumper



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101



CONDITION REPORT



Report No:
2017303373
DATE
25/09/2026



Engine



Fan Belt



Radiator Cross Member



Tyre Rear Left



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100861101