




CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	LJZ604NW
Model	KWID	Register Number	
VIN	MEEBBA00300790886	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2027
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	181,780 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:

2017305417

DATE

30/09/2026

Damage

Repair Way

Tail Light Right Damaged	Replace
Seat Rear Torn / Cut	Repair
Door Handle Front Right Damaged	Repair
Carpet Rear Dirty	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Smooth	Replace
Vehicle dirty inside	Repair
Boot not opening can not see spare wheel	Repair
Rear hub caps missing	Replace
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.4	2.4	-	
Rear	1.0	1.0	-	
Emergency / Parking	0.7	0.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Invovic	El601	V	3425	0 mm
Front Right	175/65R14	82H	Invovic	El601	V	2225	0 mm
Rear Left	175/70R14	84H	Powertrac	Adams	V	0325	0 mm
Rear Right	185/60R14	82H	Continental	Contact	V	1915	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE	DTC010664	INLET PRESSURE CONSISTENCY VALUE OUTSIDE TOLERANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026

[illegible]

Shock and brake report

[illegible]

Diagnostic report

1991年12月	1992年1月	1992年2月	1992年3月	1992年4月	1992年5月	1992年6月	1992年7月	1992年8月	1992年9月	1992年10月	1992年11月	1992年12月
1991.12.1	1991.12.2	1991.12.3	1991.12.4	1991.12.5	1991.12.6	1991.12.7	1991.12.8	1991.12.9	1991.12.10	1991.12.11	1991.12.12	1991.12.13
1991.12.14	1991.12.15	1991.12.16	1991.12.17	1991.12.18	1991.12.19	1991.12.20	1991.12.21	1991.12.22	1991.12.23	1991.12.24	1991.12.25	1991.12.26
1991.12.27	1991.12.28	1991.12.29	1991.12.30	1991.12.31	1992.1.1	1992.1.2	1992.1.3	1992.1.4	1992.1.5	1992.1.6	1992.1.7	1992.1.8
1992.1.9	1992.1.10	1992.1.11	1992.1.12	1992.1.13	1992.1.14	1992.1.15	1992.1.16	1992.1.17	1992.1.18	1992.1.19	1992.1.20	1992.1.21
1992.1.22	1992.1.23	1992.1.24	1992.1.25	1992.1.26	1992.1.27	1992.1.28	1992.1.29	1992.1.30	1992.1.31	1992.2.1	1992.2.2	1992.2.3
1992.2.4	1992.2.5	1992.2.6	1992.2.7	1992.2.8	1992.2.9	1992.2.10	1992.2.11	1992.2.12	1992.2.13	1992.2.14	1992.2.15	1992.2.16
1992.2.17	1992.2.18	1992.2.19	1992.2.20	1992.2.21	1992.2.22	1992.2.23	1992.2.24	1992.2.25	1992.2.26	1992.2.27	1992.2.28	1992.2.29
1992.2.30	1992.3.1	1992.3.2	1992.3.3	1992.3.4	1992.3.5	1992.3.6	1992.3.7	1992.3.8	1992.3.9	1992.3.10	1992.3.11	1992.3.12
1992.3.13	1992.3.14	1992.3.15	1992.3.16	1992.3.17	1992.3.18	1992.3.19	1992.3.20	1992.3.21	1992.3.22	1992.3.23	1992.3.24	1992.3.25
1992.3.26	1992.3.27	1992.3.28	1992.3.29	1992.3.30	1992.3.31	1992.4.1	1992.4.2	1992.4.3	1992.4.4	1992.4.5	1992.4.6	1992.4.7
1992.4.8	1992.4.9	1992.4.10	1992.4.11	1992.4.12	1992.4.13	1992.4.14	1992.4.15	1992.4.16	1992.4.17	1992.4.18	1992.4.19	1992.4.20
1992.4.21	1992.4.22	1992.4.23	1992.4.24	1992.4.25	1992.4.26	1992.4.27	1992.4.28	1992.4.29	1992.4.30	1992.5.1	1992.5.2	1992.5.3
1992.5.4	1992.5.5	1992.5.6	1992.5.7	1992.5.8	1992.5.9	1992.5.10	1992.5.11	1992.5.12	1992.5.13	1992.5.14	1992.5.15	1992.5.16
1992.5.17	1992.5.18	1992.5.19	1992.5.20	1992.5.21	1992.5.22	1992.5.23	1992.5.24	1992.5.25	1992.5.26	1992.5.27	1992.5.28	1992.5.29
1992.5.30	1992.5.31	1992.6.1	1992.6.2	1992.6.3	1992.6.4	1992.6.5	1992.6.6	1992.6.7	1992.6.8	1992.6.9	1992.6.10	1992.6.11
1992.6.12	1992.6.13	1992.6.14	1992.6.15	1992.6.16	1992.6.17	1992.6.18	1992.6.19	1992.6.20	1992.6.21	1992.6.22	1992.6.23	1992.6.24
1992.6.25	1992.6.26	1992.6.27	1992.6.28	1992.6.29	1992.6.30	1992.7.1	1992.7.2	1992.7.3	1992.7.4	1992.7.5	1992.7.6	1992.7.7
1992.7.8	1992.7.9	1992.7.10	1992.7.11	1992.7.12	1992.7.13	1992.7.14	1992.7.15	1992.7.16	1992.7.17	1992.7.18	1992.7.19	1992.7.20
1992.7.21	1992.7.22	1992.7.23	1992.7.24	1992.7.25	1992.7.26	1992.7.27	1992.7.28	1992.7.29	1992.7.30	1992.7.31	1992.8.1	1992.8.2
1992.8.3	1992.8.4	1992.8.5	1992.8.6	1992.8.7	1992.8.8	1992.8.9	19					


Diagnostic report

[illegible]

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886




CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886




CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



Oil cap and dipstick



Seat Rear



Carpet Rear



Door Handle Front Right



Tail Light Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



Bonnet



Front Fender Right



Door Rear Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



Door Front Left



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886



CONDITION REPORT



Report No:
2017305417
DATE
30/09/2026



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00300790886