



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	01/10/2026		M57 Pretoria Road - 1619
Inspection Date	01/10/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	KY01LLGP
Model	KIGER	Register Number	
VIN	MEEHBC00500077588	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	SILVER	Power / Displacement	
Year Model	2022	Paint Finish	M - METALLIC
Km Reading	77,572 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



Damage

Repair Way

Door Hinges Front Left Damaged	Replace
Side Mirror Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Tyre Rear Left Smooth	Replace
Warning lights illuminated	Repair
Vehicle idling while testing / Battery	Repair
Front tyre size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.9	3.3	-	
Rear	1.1	1.1	-	
Emergency / Parking	1.2	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/60R16	92H	Ceat	Securadrive	V	2422	1 mm
Front Right	195/60R16	89V	ceat	Securadrive	V	2422	5 mm
Rear Left	195/60R16	89V	Ceat	Securadrive	V	4222	0 mm
Rear Right	195/60R16	89V	Ceat	Securadrive	V	4222	1 mm
Spare	165/80R14	85R	Ceat	Temporary	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INSTRUMENT PANEL	DTC94037B	BRAKE FLUID LEVEL CIRCUIT LOW FLUID LEVEL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. BODY EXTERIOR - RESIDUAL TRACES OF POOR REPAIR ON BODY PANELS / SIGNS OF SPRAY WORK DONE ON BODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Expansion bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT




Report No:


Report No.
2017305787

DATE _____


01/10/2026



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Sparewheel

Car				Car			
Make/Mod.	BMW			Make/Mod.	BMW 318i		
Year	1994			Year	1994		
Color	Black			Color	Black		
Engine	2.0L I4			Engine	2.0L I4		
Transmission	Manual			Transmission	Manual		
Drive type	FWD			Drive type	FWD		
MPG (city/hwy)	24/34			MPG (city/hwy)	24/34		
MSRP	\$12,000			MSRP	\$12,000		
Test results				Test results			
Side-impact test				Side-impact test			
Passes side-impact test	Yes			Passes side-impact test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			
Passes crash test	Yes			Passes crash test	Yes		
Crash test results				Crash test results			

Shock and brake report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEHBC00500077588




CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



Diagnostic Report page 1



Diagnostic Report page 2



Warning lights illuminated



Side Mirror Left



Door Hinges Front Left



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588



CONDITION REPORT



Report No:
2017305787
DATE
01/10/2026



Door Front Left



Front Fender Left



Door Front Right



Bonnet



Front Bumper



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEHBC00500077588