



## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 12/06/2025        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 12/06/2025        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |              |
|-----------------|-------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        |              |
| Manufacturer    | KIA               | Registration Number     | JN59CMGP     |
| Model           | SELTOS            | Register Number         |              |
| VIN             | MZBER814MLN085967 | Date Of First Licensing |              |
| Engine Number   |                   | Last COR                |              |
| Doors           | 5                 | License Expiry Date     | 30/06/2025   |
| Color           | WHITE             | Power / Displacement    |              |
| Year Model      |                   | Paint Finish            | M - METALLIC |
| Km Reading      | 128,145 KM        | Fuel                    | PETROL       |
| Cab / Body Type | STATION WAGON     | Transmission            | AUTOMATIC    |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967




CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025

| Damage                                | Repair Way |
|---------------------------------------|------------|
| Front Bumper Paintwork • Scratched    | Repair     |
| Bonnet Paintwork • Chipmarks          | Repair     |
| Rear Fender Left Dented               | Repair     |
| Door Front Left Paintwork • Chipmarks | Repair     |
| Door Rear Left Dented                 | Repair     |



Brakes  
Brake Test Results

|                     | Left               | Right              |                  |                     |
|---------------------|--------------------|--------------------|------------------|---------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| Front               | 2.9                | 3.0                | -                |                     |
| Rear                | 2.1                | 2.2                | -                |                     |
| Emergency / Parking | 1.2                | 1.4                | -                |                     |

Tyres and Rims  
Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model    | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left  | 215/60R17 | 96H              | Dunlop      | Sp sport | V     | 0323            | 3 mm             |
| Front Right | 215/60R17 | 96H              | Dunlop      | Sp sport | V     | 0323            | 3 mm             |
| Rear Left   | 215/60R17 | 96H              | Dunlop      | Sp sport | V     | 0323            | 3 mm             |
| Rear Right  | 215/60R17 | 96H              | Dunlop      | Sp sport | V     | 0323            | 3 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967



## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System  | Code     | Description         | Status |
|----|---------|----------|---------------------|--------|
| 1  | HISTORY | C1102:16 | BATTERY VOLTAGE LOW |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967



## CONDITION REPORT



**Report No:**  
**2016911156**  
**DATE**  
**12/06/2025**

[illegible]

## Shock and brake report

|   |                               |     |
|---|-------------------------------|-----|
|  | Microsoft Word 2003 中文版       | 98  |
|  | Microsoft Excel 2003 中文版      | 99  |
|  | Microsoft PowerPoint 2003 中文版 | 100 |
|  | Microsoft Access 2003 中文版     | 101 |
|  | Microsoft Project 2003 中文版    | 102 |
|  | Microsoft Visio 2003 中文版      | 103 |
|  | Microsoft Publisher 2003 中文版  | 104 |
|  | Microsoft Office 2003 中文版     | 105 |
|  | Microsoft Office 2003 中文版     | 106 |
|  | Microsoft Office 2003 中文版     | 107 |
|  | Microsoft Office 2003 中文版     | 108 |
|  | Microsoft Office 2003 中文版     | 109 |
|  | Microsoft Office 2003 中文版     | 110 |
|  | Microsoft Office 2003 中文版     | 111 |
|  | Microsoft Office 2003 中文版     | 112 |
|  | Microsoft Office 2003 中文版     | 113 |
|  | Microsoft Office 2003 中文版     | 114 |
|  | Microsoft Office 2003 中文版     | 115 |
|  | Microsoft Office 2003 中文版     | 116 |
|  | Microsoft Office 2003 中文版     | 117 |
|  | Microsoft Office 2003 中文版     | 118 |
|  | Microsoft Office 2003 中文版     | 119 |
|  | Microsoft Office 2003 中文版     | 120 |
|  | Microsoft Office 2003 中文版     | 121 |
|  | Microsoft Office 2003 中文版     | 122 |
|  | Microsoft Office 2003 中文版     | 123 |
|  | Microsoft Office 2003 中文版     | 124 |
|  | Microsoft Office 2003 中文版     | 125 |
|  | Microsoft Office 2003 中文版     | 126 |
|  | Microsoft Office 2003 中文版     | 127 |
|  | Microsoft Office 2003 中文版     | 128 |
|  | Microsoft Office 2003 中文版     | 129 |
|  | Microsoft Office 2003 中文版     | 130 |
|  | Microsoft Office 2003 中文版     | 131 |
|  | Microsoft Office 2003 中文版     | 132 |
|  | Microsoft Office 2003 中文版     | 133 |
|  | Microsoft Office 2003 中文版     | 134 |
|  | Microsoft Office 2003 中文版     | 135 |
|  | Microsoft Office 2003 中文版     | 136 |
|  | Microsoft Office 2003 中文版     | 137 |
|  | Microsoft Office 2003 中文版     | 138 |
|  | Microsoft Office 2003 中文版     | 139 |
|  | Microsoft Office 2003 中文版     | 140 |
|  | Microsoft Office 2003 中文版     | 141 |
|  | Microsoft Office 2003 中文版     | 142 |
|  | Microsoft Office 2003 中文版     | 143 |
|  | Microsoft Office 2003 中文版     | 144 |
|  | Microsoft Office 2003 中文版     | 145 |
|  | Microsoft Office 2003 中文版     | 146 |
|  | Microsoft Office 2003 中文版     | 147 |
|  | Microsoft Office 2003 中文版     | 148 |
|  | Microsoft Office 2003 中文版     | 149 |
|  | Microsoft Office 2003 中文版     | 150 |
|  | Microsoft Office 2003 中文版     | 151 |
|  | Microsoft Office 2003 中文版     | 152 |
|  | Microsoft Office 2003 中文版     | 153 |
|  | Microsoft Office 2003 中文版     | 154 |
|  | Microsoft Office 2003 中文版     | 155 |
|  | Microsoft Office 2003 中文版     | 156 |
|  | Microsoft Office 2003 中文版     | 157 |
|  | Microsoft Office 2003 中文版     | 158 |
|  | Microsoft Office 2003 中文版     | 159 |
|  | Microsoft Office 2003 中文版     | 160 |
|  | Microsoft Office 2003 中文版     | 161 |
| <   |                               |     |

第 1 页 共 1 页

1/1

## Diagnostic report

[illegible]

## Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MZBER814MLN085967



## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967






## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No spare wheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MZBER814MLN085967




## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967





## CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025



Coolant bottle



Water level



Bonnet



Front Bumper



Front Bumper



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MZBER814MLN085967





CONDITION REPORT



Report No:  
2016911156  
DATE  
12/06/2025



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MZBER814MLN085967