



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/01/2024		M57 Pretoria Road - 1619
Inspection Date	11/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	KGZ758NW
Model	QASHQAI	Register Number	
VIN	SJNFBAJ10Z2924262	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	29/02/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	268,911 KM	Fuel	PETROL
Cab / Body Type	SUV	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Replace
Caps Missing	Repair
Battery box Defective	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Steering Rack Boot Left Damaged	Replace
Steering Rack Boot Right Damaged	Replace
Shock Absorber Front Left Worn	Replace
Shock Absorber Front Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Right Damaged	Replace
Engine mountings Damaged	Replace
Gearbox Mountings Damaged	Replace
Gearbox Oil Leak	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFBAJ10Z2924262



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Damage	Repair Way
Radiator Cradle Damaged	Replace
Engine Performance Insufficient	Repair
Engine Noise Idling / Hunting	Repair
Engine Smoke Excessive	Repair
Clutch Operation Insufficient	Repair

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	3.27	3.39	-	
Rear	2.28	2.3	-	
Emergency / Parking	1.71	1.28	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R18	98V	Michelin	Radial	V	5019	0 mm
Front Right	225/55R18	98V	Michelin	Radial	V	0820	0 mm
Rear Left	235/60R18	103H	Michelin	Radial	V	3118	1 mm
Rear Right	235/60R18	103V	Goodride	Radial	V	1522	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ENGINE MANAGEMENT LIGHTS ILLUMINATED ON CLUSTER. VEHICLE ELECTRONICS MALFUNCTIONING.Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to some body panels. Signs of impact damage to front of vehi

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
ACCORDING TO THE AGE AND
MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND
MECHANICAL PARTS.

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

VIN: S1NRAJ1076225165

2 / 13

DATE


11/01/2024



Brake and shock test




Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016225165

VIN: SJNFBAJ10Z2924262

DATE

11/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
17/01/2024
VIN: SJNFBAJ107012024
4 / 13



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

VIN: SJNFBAJ10Z2924262

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024


VIN: SJNFBAJ10Z2924262
6 / 13



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

VIN: SJNFBAJ10Z2924262
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

ENGINE 1



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 10



ADDITIONAL 11



Engine Wiring



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

VIN: SJNFBAJ10Z2924262
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Engine Wiring



Water level

VIN: 2016225165
10 / 13

Gearbox Mountings



Engine mountings



Caps



Engine



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

VIN: SJNFBAJ10Z2924262

11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Front Bumper




Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

VIN: SJNFBAJ10Z2924262
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Door Rear Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Door Rear Right



Door Front Right



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Rear Fender Right



Front Fender Right




Seat Front Right



Seat Rear



Seat Front Left



Tyre Rear Right



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Tyre Front Left



Tyre Front Right



Gearbox Mountings



Battery box



Radiator Cradle



Engine



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

Gearbox



Steering Rack Boot Right



Steering Rack Boot Left



Shock Absorber Front Left



Shock Absorber Front Right



CONDITION REPORT

Report No: 2016225165

DATE
11/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za