



CONDITION REPORT



Report No:

2017299328

DATE

16/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/09/2026		M57 Pretoria Road - 1619
Inspection Date	16/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	MH00ZKGP
Model	I30 N	Register Number	
VIN	TMAHC51AVPJ037777	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2027
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	40,736 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:

2017299328

DATE

16/09/2026

Damage

Repair Way

Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Chipmarks	Repair
Rear Fender Left Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Weather Strip Door Front Left Defective	Repair
Weather Strip Door Rear Left Defective	Repair
Windscreen Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Belly plates Damaged	Repair
Warning light illuminated on dashboard	Repair



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.33	4.26	-	
Rear	2.69	2.74	-	
Emergency / Parking	2.2	1.74	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/35 R19	91Y	GT Radial	Sport Active	V	1625	0 mm
Front Right	235/35 R19	91Y	GT Radial	Sport Active	V	1625	0 mm
Rear Left	235/35 R19	91Y	GT Radial	Sport Active	V	3424	2 mm
Rear Right	235/35 R19	91Y	GT Radial	Sport Active	V	2925	2 mm
Spare	T125/70 R18	99M	Kumho	Temporary	V	2022	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777

**CONDITION REPORT**

Report No:

2017299328

DATE

16/09/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:

2017299328

DATE _____

16/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

Part No. (30-00000000-01-000)	Part Name	Part No. (30-00000000-01-000)
MP-0 (Multi-Function Camera)	AD65	0
WPC (Wireless Power Charger)		0
WPCU (Integrated Gateway Power Control Module)		0
PLS0 (Electronic Limited Slip Differential)		0
SR (Electronic Sound Generator)		0

OTD (0)

Technician Notes
 2017-01-28

Customer Name: _____

Technician: _____

Date: _____

Note: This is a copy of the original document.

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:
2017299328
DATE
16/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT




Report No:
2017299328
DATE
16/09/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:

2017299328

DATE

16/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:
2017299328
DATE
16/09/2026



Front Fender Left



Front Fender Left



Windscreen



Weather Strip Door Front Left



Weather Strip Door Rear Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:

2017299328

DATE

16/09/2026



Front Fender Right / Inner Tray



Front Bumper



Front Bumper



Front Bumper



Door Rear Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777




CONDITION REPORT



Report No:
2017299328
DATE
16/09/2026



Rear Fender Left



Rear Fender Left



Rim Rear Left



Rim Rear Right



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777



CONDITION REPORT



Report No:
2017299328
DATE
16/09/2026



Tyre Front Right



Tyre Front Left



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: TMAHC51AVPJ037777