



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/02/2024		M57 Pretoria Road - 1619
Inspection Date	28/02/2024		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	AUDI	Registration Number	CW45FNGP
Model	A4	Register Number	
VIN	WAUZZZ8K1EA056020	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/11/2023
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	257,302 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Expansion Bottle Water Leak	Replace
Water level Insufficient	Repair
Bonnet stay and shocks Defective	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Seat Front Right Cracked	Repair
Side Mirror Right Paintwork • Flaking	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Defective	Replace
Brake disc 1. Axle right Defective	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
ABS and traction control light on	Repair
Front suspension noisy	Repair
Body exterior	Signs of spray work done on some body panels



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

### Brakes

#### Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [kN]	Braking Force [kN]		
Front	3.8	4.1	-	-
Rear	2.9	2.7	-	-
Emergency / Parking	2.1	1.2	-	-

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R16	95V	Dunlop	Sp sport	V	3321	2 mm
Front Right	225/55R16	95V	Dunlop	Sp sport	V	3321	3 mm
Rear Left	225/55R16	95V	Dunlop	Sp sport	V	3321	3 mm
Rear Right	225/55R16	95V	Dunlop	Sp sport	V	3421	3 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



## CONDITION REPORT


VIN: WVAH7M38100050090

Report No: 2016284790

2 / 12

DATE

28/02/2024



Shock and brake report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



## CONDITION REPORT

Report No: 2016284790

VIN: WAUZZZ8K1EA056020

DATE

28/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE

VIN: WAUZZZ81502500000

28/02/2024

4 / 12



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

VIN: WAUZZZ8K1EA056020

5 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

VIN: WAUZZZ8K1EA056020

6 / 12



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

VIN: WAUZZZ8K1EA056020

7 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

No spare wheel



8 / 12



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024


VIN: WAUZZZ8K1EA056020

9 / 12




## CONDITION REPORT


Report No: 2016284790

DATE  
28/02/2024


Automatic



Oil cap




Expansion bottle



Parking Brake Performance



Water level



Bonnet stay and shocks



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

VIN: WAUZZZ8K1EA056020

11 / 12



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

Bonnet



Windscreen



Side Mirror Right



Seat Front Right



Door Rear Right



Door Front Right



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

Front Fender Right



Front Bumper



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Engine



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

Engine



Brake disc 1. Axle right



Brake disc 1. Axle left



Center Console / Cubbyhole + Lid



Expansion Bottle



## CONDITION REPORT

Report No: 2016284790

DATE  
28/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)