



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/07/2025		M57 Pretoria Road - 1619
Inspection Date	25/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	BMW	Registration Number	ZTW907GP
Model	320I COUPE AT [2010-2014]	Register Number	
VIN	WBAKD52090E492373	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/03/2025
Color	WHITE	Power / Displacement	
Year Model	2010	Paint Finish	TWO COAT UNI
Km Reading	258,789 KM	Fuel	PETROL
Cab / Body Type	COUPE	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Damage	Repair Way
Engine Oil Leak	Repair
Bonnet stay and shocks Damaged	Repair
Switch Electrical Window Winder front right Damaged	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Tyre Front Left Worn	Repair
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Gearbox Oil Leak	Repair
Engine Smoke Excessive	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.06	2.91	-	
Rear	2.48	2.62	-	
Emergency / Parking	2.17	2.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/40R18	97Y	Pirelli	Radial	V	0314	0 mm
Front Right	225/45R18	91Y	Continental	Contisport	V	0617	0 mm
Rear Left	245/40R18	91Y	Continental	Contisport	V	3819	0 mm
Rear Right	245/40R18	97Y	Pirelli	Radial	V	4417	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. VEHICLE ELECTRONICS MALFUNCTIONING. Interior: signs of vehicle airbags deployed. passenger side cup holder damaged.

Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Vehicle body in poor condition.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025

Vehicle Information			
Make	Model	Year	Color
BMW	3 Series	2016	White
Engine	Transmission	Drive	Registration
2.0L	Automatic	FWD	123456789
Brake and Shock Absorber Data			
Wheel	Brake Pad	Shock Absorber	Notes
Front Left	Good	Good	
Front Right	Good	Good	
Rear Left	Good	Good	
Rear Right	Good	Good	

Brake and shock absorber

Diagnostic Results	
System	Status
Engine	Pass
Transmission	Pass
Brake	Pass
Steering	Pass
Electrical	Pass
Suspension	Pass
Exhaust	Pass
Lighting	Pass
Wipers	Pass
Windows	Pass
Doors	Pass
Seats	Pass
Interior	Pass
Exterior	Pass
Overall	Pass

Diagnostic.

Diagnostic Results	
System	Status
Engine	Pass
Transmission	Pass
Brake	Pass
Steering	Pass
Electrical	Pass
Suspension	Pass
Exhaust	Pass
Lighting	Pass
Wipers	Pass
Windows	Pass
Doors	Pass
Seats	Pass
Interior	Pass
Exterior	Pass
Overall	Pass

Diagnostic.

Diagnostic Results	
System	Status
Engine	Pass
Transmission	Pass
Brake	Pass
Steering	Pass
Electrical	Pass
Suspension	Pass
Exhaust	Pass
Lighting	Pass
Wipers	Pass
Windows	Pass
Doors	Pass
Seats	Pass
Interior	Pass
Exterior	Pass
Overall	Pass

Diagnostic.

Diagnostic Results	
System	Status
Engine	Pass
Transmission	Pass
Brake	Pass
Steering	Pass
Electrical	Pass
Suspension	Pass
Exhaust	Pass
Lighting	Pass
Wipers	Pass
Windows	Pass
Doors	Pass
Seats	Pass
Interior	Pass
Exterior	Pass
Overall	Pass

Diagnostic.



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBKAD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Oil cap and dipstick.



Water level



Bonnet stay and shocks



Front Bumper



Front Bumper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Front Fender Left



Door Front Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Rear Fender Right



Front Fender Right



Door Front Right



Roof



Seat Front Right



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Tyre Rear Left



Tyre Front Left



Tyre Front Right



Engine



Gearbox



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373



CONDITION REPORT



Report No:
2016957974
DATE
25/07/2025



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBAKD52090E492373