



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	20/08/2026		M57 Pretoria Road - 1619
Inspection Date	19/08/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MERCEDES-BENZ	Registration Number	HM02CVGP
Model	AMG V8	Register Number	
VIN	WDD2220772A114123	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/08/2026
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	87,939 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



Damage

Repair Way

Engine Oil Leak	Repair
Electrical Window Winder front right Defective	Repair
Seat Rear Worn	Repair
Front Bumper Damaged	Repair
Grill Paintwork • Flaking	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Repair
Back Window Damaged	Repair
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	5.38	5.29	-	
Rear	4.34	5.03	-	
Emergency / Parking	3.43	3.99	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R20	97W	Sailun	Radial	V	4825	3 mm
Front Right	255/40R20	101W	Michelin	Radial	V	0822	0 mm
Rear Left	285/35R20	104Y	Continental	Contisport	V	1422	0 mm
Rear Right	285/35R20	104Y	Continental	Contisport	V	1322	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	TCM	U010300	PLEASE REFER TO VEHICLE SERVICE MANUAL.	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:

2017286821

DATE _____

19/08/2026

[illegible]

Brake test.

[illegible]

Diagnostic.

[illegible]

Diagnostic.

Question type	Question	Answer
Multiple choice	1. Which of the following is not a function of the liver?	B
Multiple choice	2. Which of the following is not a function of the liver?	C
Multiple choice	3. Which of the following is not a function of the liver?	D
Multiple choice	4. Which of the following is not a function of the liver?	E
Multiple choice	5. Which of the following is not a function of the liver?	F
Multiple choice	6. Which of the following is not a function of the liver?	G
Multiple choice	7. Which of the following is not a function of the liver?	H
Multiple choice	8. Which of the following is not a function of the liver?	I
Multiple choice	9. Which of the following is not a function of the liver?	J
Multiple choice	10. Which of the following is not a function of the liver?	K
Multiple choice	11. Which of the following is not a function of the liver?	L
Multiple choice	12. Which of the following is not a function of the liver?	M
Multiple choice	13. Which of the following is not a function of the liver?	N
Multiple choice	14. Which of the following is not a function of the liver?	O
Multiple choice	15. Which of the following is not a function of the liver?	P
Multiple choice	16. Which of the following is not a function of the liver?	Q
Multiple choice	17. Which of the following is not a function of the liver?	R
Multiple choice	18. Which of the following is not a function of the liver?	S
Multiple choice	19. Which of the following is not a function of the liver?	T
Multiple choice	20. Which of the following is not a function of the liver?	U
Multiple choice	21. Which of the following is not a function of the liver?	V
Multiple choice	22. Which of the following is not a function of the liver?	W
Multiple choice	23. Which of the following is not a function of the liver?	X
Multiple choice	24. Which of the following is not a function of the liver?	Y
Multiple choice	25. Which of the following is not a function of the liver?	Z

Diagnostic.

[illegible]

Diagnostic.

[illegible]

Diagnostic.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WDD2220772A114123




CONDITION REPORT




Report No:
2017286821
DATE
19/08/2026




Diagnostic.



Diagnostic.




Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:

2017286821

DATE

19/08/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



Front Bumper



Front Bumper



Grill



Rear bumper



Rear bumper



Back Window

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



Boot Lid / Hatch door



Windscreen



Electrical Window Winder front right



Seat Rear



Engine



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123



CONDITION REPORT



Report No:
2017286821
DATE
19/08/2026



Tyre Rear Right



Tyre Rear Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2220772A114123