



CONDITION REPORT



Report No:

2017290028

DATE

26/08/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	26/08/2026		M57 Pretoria Road - 1619
Inspection Date	26/08/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	FF26GHGP
Model	FOCUS 1.0 ECOBOOST TREND POWERSHIFT [2016-2018]	Register Number	
		Date Of First Licensing	
VIN	WF04XXGCC4FM63312	Last COR	
Engine Number		License Expiry Date	31/08/2026
Doors	4	Power / Displacement	
Color	SILVER	Paint Finish	M - METALLIC
Year Model	2016	Fuel	PETROL
Km Reading	204,373 KM	Transmission	AUTOMATIC
Cab / Body Type	SEDAN		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:

2017290028


DATE

26/08/2026

Damage

Repair Way

Seat Front Right Torn / Cut	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Engine light illuminated	Repair



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.9	3.4	-	
Rear	2.2	2.5	-	
Emergency / Parking	1.6	1.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Autogrip	P308 plus	V	4724	3 mm
Front Right	205/55R16	91V	Autogrip	P308 plus	V	1425	3 mm
Rear Left	205/55R16	91V	Autogrip	P308 plus	V	4724	3 mm
Rear Right	205/55R16	91V	Autogrip	P308 plus	V	0125	3 mm
Spare	T125/90R16	98M	Hankook	Temporary	V	3215	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	P00C6:00-28	FUEL RAIL PRESSURE TOO LOW -ENGINE CRANKING BANK 1	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026

[illegible]

Shock and brake report

[illegible]

Diagnostic report

1990-1991		1991-1992	
1. <i>Chrysomelidae</i> (1990-1991)	1990	1991	
2. <i>Chrysomelidae</i> (1991-1992)	1991	1992	
3. <i>Chrysomelidae</i> (1992-1993)	1992	1993	
4. <i>Chrysomelidae</i> (1993-1994)	1993	1994	
5. <i>Chrysomelidae</i> (1994-1995)	1994	1995	
6. <i>Chrysomelidae</i> (1995-1996)	1995	1996	
7. <i>Chrysomelidae</i> (1996-1997)	1996	1997	
8. <i>Chrysomelidae</i> (1997-1998)	1997	1998	
9. <i>Chrysomelidae</i> (1998-1999)	1998	1999	
10. <i>Chrysomelidae</i> (1999-2000)	1999	2000	
11. <i>Chrysomelidae</i> (2000-2001)	2000	2001	
12. <i>Chrysomelidae</i> (2001-2002)	2001	2002	
13. <i>Chrysomelidae</i> (2002-2003)	2002	2003	
14. <i>Chrysomelidae</i> (2003-2004)	2003	2004	
15. <i>Chrysomelidae</i> (2004-2005)	2004	2005	
16. <i>Chrysomelidae</i> (2005-2006)	2005	2006	
17. <i>Chrysomelidae</i> (2006-2007)	2006	2007	
18. <i>Chrysomelidae</i> (2007-2008)	2007	2008	
19. <i>Chrysomelidae</i> (2008-2009)	2008	2009	
20. <i>Chrysomelidae</i> (2009-2010)	2009	2010	
21. <i>Chrysomelidae</i> (2010-2011)	2010	2011	
22. <i>Chrysomelidae</i> (2011-2012)	2011	2012	
23. <i>Chrysomelidae</i> (2012-2013)	2012	2013	
24. <i>Chrysomelidae</i> (2013-2014)	2013	2014	
25. <i>Chrysomelidae</i> (2014-2015)	2014	2015	
26. <i>Chrysomelidae</i> (2015-2016)	2015	2016	
27. <i>Chrysomelidae</i> (2016-2017)	2016	2017	
28. <i>Chrysomelidae</i> (2017-2018)	2017	2018	
29. <i>Chrysomelidae</i> (2018-2019)	2018	2019	
30. <i>Chrysomelidae</i> (2019-2020)	2019	2020	
31. <i>Chrysomelidae</i> (2020-2021)	2020	2021	
32. <i>Chrysomelidae</i> (2021-2022)	2021	2022	
33. <i>Chrysomelidae</i> (2022-2023)	2022	2023	
34. <i>Chrysomelidae</i> (2023-2024)	2023	2024	
35. <i>Chrysomelidae</i> (2024-2025)	2024	2025	
36. <i>Chrysomelidae</i> (2025-2026)	2025	2026	
37. <i>Chrysomelidae</i> (2026-2027)	2026	2027	
38. <i>Chrysomelidae</i> (2027-2028)	2027	2028	
39. <i>Chrysomelidae</i> (2028-2029)	2028	2029	
40. <i>Chrysomelidae</i> (2029-2030)	2029	2030	
41. <i>Chrysomelidae</i> (2030-2031)	2030	2031	
42. <i>Chrysomelidae</i> (2031-2032)	2031	2032	
43. <i>Chrysomelidae</i> (2032-2033)	2032	2033	
44. <i>Chrysomelidae</i> (2033-2034)	2033	2034	
45. <i>Chrysomelidae</i> (2034-2035)	2034	2035	
46. <i>Chrysomelidae</i> (2035-2036)	2035	2036	
47. <i>Chrysomelidae</i> (2036-2037)	2036	2037	
48. <i>Chrysomelidae</i> (2037-2038)	2037	2038	
49. <i>Chrysomelidae</i> (2038-2039)	2038	2039	
50. <i>Chrysomelidae</i> (2039-2040)	2039	2040	
51. <i>Chrysomelidae</i> (2040-2041)	2040	2041	
52. <i>Chrysomelidae</i> (2041-2042)	2041	2042	
53. <i>Chrysomelidae</i> (2042-2043)	2042	2043	
54. <i>Chrysomelidae</i> (2043-2044)	2043	2044	
55. <i>Chrysomelidae</i> (2044-2045)	2044	2045	
56. <i>Chrysomelidae</i> (2045-2046)	2045	2046	
57. <i>Chrysomelidae</i> (2046-2047)	2046	2047	
58. <i>Chrysomelidae</i> (2047-2048)	2047	2048	
59. <i>Chrysomelidae</i> (2048-2049)	2048	2049	
60. <i>Chrysomelidae</i> (2049-2050)	2049	2050	
61. <i>Chrysomelidae</i> (2050-2051)	2050	2051	
62. <i>Chrysomelidae</i> (2051-2052)	2051	2052	
63. <i>Chrysomelidae</i> (2052-2053)	2052	2053	
64. <i>Chrysomelidae</i> (2053-2054)	2053	2054	
65. <i>Chrysomelidae</i> (2054-2055)	2054	2055	
66. <i>Chrysomelidae</i>			

Diagnostic report

[illegible]

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:

2017290028

DATE

26/08/2026



90 DEGREE REAR




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026



Oil cap and dipstick



Expansion bottle



Water level



Seat Front Right



Windscreen



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312



CONDITION REPORT



Report No:
2017290028
DATE
26/08/2026



Door Rear Right



Door Front Right



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF04XXGCC4FM63312