



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	18/03/2024		M57 Pretoria Road - 1619
Inspection Date	18/03/2024		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MINI	Registration Number	JG15TBGP
Model	COOPER JCW CLUBMAN	Register Number	
VIN	WMWLV920602G34529	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2024
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	193,199 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



Damage	Repair Way
Center Console / Cubbyhole + Lid Damaged	Repair
Number Plate Front Missing	Replace
Number Plate Rear Missing	Replace
Front Bumper Paintwork • Scratched	Repair
Grill Cracked	Repair
Bonnet Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Tyre Rear Right Defective	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Both number plate missing	Replace
Airbag and brake light on	Repair



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

### Brakes

#### Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	-	-	-	-
Rear	-	-	-	-
Emergency / Parking	-	-	-	-

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R18	92H	Kenda	Kaiser	V	2020	4 mm
Front Right	225/40R18	92Y	Pirelli	Cinturato	V	2722	4 mm
Rear Left	225/40R18	92Y	General	Altimax	V	3622	4 mm
Rear Right	225/40R18	92W	Autogrip	Grip 200	V	3122	4 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR



90 DEGREE FRONT



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WMWLV920602G34529

4 / 10



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Automatic



Explantion bottle



Oil cap and dipstick



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WMWLV920602G34529  
6 / 10



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 1



ENGINE 2



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WMWLV920602G34529  
8 / 10



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024


CHASSIS




VIN PLATE OR STICKER



LICENSE DISC



SHOCK REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DIAGNOSTIC REPORT PAGE 3



Center Console / Cubbyhole + Lid



Water level



Door Rear Right



Door Front Right



Front Bumper



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

Front Bumper



Grill



Number Plate Front



Door Front Left



Door Rear Left



Rear Fender Left



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

Rear bumper



Rear bumper



Number Plate Rear



Rear Fender Right



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right



Tyre Rear Right



Bonnet



Windscreen



## CONDITION REPORT

Report No: 2016309534

DATE  
18/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)